

St Mary's Catholic Primary
School

ICT documentation & information

Produced by: Empowered Learning.

Introduction




The purpose of this documentation is to provide detailed information outlining the ICT network and infrastructure.

Within this document you will find;

- * Clearly documented and labelled ICT Room diagram.
- * Detailed hardware and software auditing on all ICT workstations and servers.
- * Important network information.
- * Imperative Mission Critical work to be carried out.
- * A report complete with suggestions for IT development and future proofing your ICT network.

This information will also act as valuable 'asset' documentation for your school.

ICT Room Diagram



PC hardware & software Audit



Computer Profile Summary

Computer Name: 1 (in PBN WORKGROUP)

Profile Date: Monday, June 23, 2003 15:51:07

Advisor Version: 6.0c

Windows Logon: admin

Operating System

Windows 98 (build 4.10.1998)

Processor ^a

225 megahertz Cyrix MII
64 kilobyte primary memory cache
512 kilobyte secondary memory cache

Drives

3.23 Gigabytes Usable Hard Drive Capacity
1.70 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
GoldStar CD-ROM CRD-8322B
Generic floppy disk drive (3.5")

Generic IDE hard disk drive (3.23 GB) -- drive 0

Logins

No details available

Installed Microsoft Hotfixes

Internet Explorer

SP1 (SP1)

[Click here](#) to see all available security Hotfixes.

Marks a HotFix that verifies correctly

System Model

Packard Bell NEC Packard Bell
Computer P070001901
System Serial Number: C417100381

Main Circuit Board ^b

Board: SiS-5598-W877F
Bus Clock: 75 megahertz
BIOS: Award Software International,
Inc. 4.51 PG 10/23/98

Memory Modules ^{c,d}

30 Megabytes Installed Memory

Slot '0' has 32 MB
Slot '1' is Empty

Local Drive Volumes

c: (on drive 0)	3.23 GB	1.70 GB free
-----------------	---------	--------------

Network Drives

mounted by admin at 06/23/03 15:50:30

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Printers

CAPTURE on FAX:
FAX BVRP
Capture fax on FAX:
BVRP Extended
HP Color on
LaserJet 4550 \\Smrcp\HP_COLOUR
PCL 6

Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
An unmarked HotFix lacks the data to allow verification

HP LaserJet Series II on LPT1:
OLICHROME Olivetti JP192 on LPT1:
SMART Print Capture Driver on FILE1:

Controllers

Standard Floppy Disk Controller
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)
SiS 5513 Dual PCI IDE Controller

Bus Adapters

SiS 7001 PCI to USB Open Host Controller

Communications

MDP3858-E Modem
ND01X Ethernet/Fast Ethernet PCI Bus Adapter
Network Card MAC Address:
00:10:A7:08:A3:59
Network IP Address: 172.19.44.30 / 24

Display

SiS 5597/5598 [Display adapter]
Packard Bell PBN 1015 [Monitor] (13.2"vis, s/n LEMN84702319, November 1998)

Multimedia

ES1869 Control Interface
ES1869 Plug and Play AudioDrive
Gameport Joystick (no joystick connected)

Other Devices

Avantis CD-ROM Controller
MDP3858 PCI Modem Enumerator
Standard 101/102-Key or Microsoft Natural Keyboard
PS2 (PS/2) [Mouse]
USB Root Hub

Software Licenses

Microsoft - Money 98	68480-OEM-1208613-23458-32137-OEM-0073614-
Microsoft - Windows 98	76554 (Key: PJ3C8-96JMW-FM2M9-8HPJG-KGHB6)
Microsoft - Word for Windows	00000-OEM-0000000-00000
Microsoft - Works 4.5	11195-OEM-0310021-81354

Software Versions

Actua Soccer 2 *	Microsoft® FrontPage(TM) Version 2.0.2.1118 *
Adobe Acrobat Version 3.0.000 *	Microsoft® Internet Services Version 6.1.33.0 *
Apple Computer, Inc. MoviePlayer Application Version 3, 0, 0, 1 *	Microsoft® NetMeeting(TM) Version 2.1
Apple Computer, Inc. PictureViewer	

Application Version 3, 0, 0, 1 [*](#)
 Avantis CD Installation Wizard Version 3.2 [*](#)
 Avantis CDsPlayer Version 3.2 [*](#)
 Avantis Ltd - CDserve Monitor Application Version 3.23 [*](#)
 Avantis Ltd. - CDserve Version 3.2 [*](#)
 Belarc, Inc. - BelManage Client Version 6.0c [*](#)
 BVRP Software - PhoneTools Version 2.10 [*](#)
 CompuServe for Windows Version 3.0 [*](#)
 Configure Media Player [*](#)
 Crick Software Ltd - CLICKER 3 Version 3.06.0007 [*](#)
 Cyber Patrol Installation [*](#)
 DK Multimedia - Children's Encyclopedia Version 1.1.0 [*](#)
 Early Victorians [*](#)
 Eastman Software, Inc., A Kodak Business - Imaging for Windows® Version 1.01.1311 [*](#)
 Event Reminder [*](#)
 Futureland [*](#)
 GOTO Software - WebEarly 98 Version 2.01 [*](#)
 InstallShield unInstaller Version 2.20.926.0 [*](#)
 JP192 Uninstall program [*](#)
 Logitech Inc. - MouseWare Version 8.02 [*](#)
 Logotron Ltd - Junior PinPoint Version 2.0.12.01 [*](#)
 Macromedia Director Version 5.0 [*](#)
 Macromedia Director Version 7.0.2 [*](#)
 Maths Explorer [*](#)
 Microsoft Corporation - Clip Gallery 3.0 for Windows Version 3.0 [*](#)
 Microsoft Corporation - Windows Internet Explorer Version 4.72.3110.0 [*](#)
 Microsoft Corporation - Windows Telephony Version 1.0.501 [*](#)
 Microsoft Encarta Version 5.33.1447 [*](#)
 Microsoft Encarta Version 6.00.43.00013 [*](#)
 Microsoft Money Version 6.00 [*](#)
 Microsoft Multimedia Viewer Version 2.00 [*](#)
 Microsoft Photo Editor Version 3.0 [*](#)
 Microsoft Windows Scripting Host Version 5.0.531.7 [*](#)
 Microsoft Works for Windows Version 4.00.03.458 [*](#)
 Microsoft® Plus! for Windows® 95 Version 4.40.500 [*](#)
 Microsoft® Chat Version 2.1 [*](#)
 * [*](#)
 Microsoft® NetShow Version 2.0.0.912 [*](#)
 Microsoft® Word for Windows® 97 Version 8.0 [*](#)
 MNYIMPRT.EXE [*](#)
 NDPS [*](#)
 Netscape Communications NSConf32 Version 4, 0, 0, 1 [*](#)
 Netscape Mail Notification [*](#)
 NETSCAPE Version 4.04 [*](#)
 Novell Client Login for 32-bit Windows Version 1.00.07 [*](#)
 Novell wm95 Version 1, 0, 0, 1 [*](#)
 Olivetti - OLICHROME (TM) Version 3.1.1 [*](#)
 Packard Bell Navigator Version 1.0.7.1 [*](#)
 Packard Bell NEC - PB SoftBar Version 2.1 [*](#)
 Packard Bell Nec, Inc. - ClickMe Version 3.2.0.0 [*](#)
 Packard Bell Tutorials Version 1.0.0.0 [*](#)
 PB NETp@ss & Registration [*](#)
 Peak Interactive EMail 100431.3430 @compuserve.com - Mathematics Version 1.00 [*](#)
 PMW.EXE [*](#)
 Print Materials [*](#)
 PrintMaster Web Site [*](#)
 Progressive Networks, Inc. - RealPlayer (32-bit) Version 4.01 Version 4.0.20.155 [*](#)
 Science Explorer II [*](#)
 Seagate Software, Inc. - Backup [*](#)
 Sherston Software Playbook [*](#)
 SMART Board Software Version 2.5.0.15 [*](#)
 SMART Board Software Version 7.1.0.15 [*](#)
 SMART Technologies Inc. - VideoPresenter Application Version 1.0.0.27 [*](#)
 Stunt Track Driver [*](#)
 Symantec Core Technology Version 19.0.0.128 [*](#)
 Symantec Corporation - Norton AntiVirus Core Technology Version 5.0.0.52 [*](#)
 Symantec Corporation - Norton AntiVirus Version 5.0.0.48 [*](#)
 Textease [*](#)
 WaterGate Software Inc. - PC-Doctor For Windows 3.0 Version 3.0 [*](#)
 ZebraSoft, Inc. - Norton Uninstall Deluxe Version 1, 0, 0, 1 [*](#)
 ZebraSoft, Inc. - SymMon Module Version 1, 0, 0, 1 [*](#)
 ôRA CREATIVE - Le Compteur Internet Européen Version 2.20 Build 0512 [*](#)

* Click to see where software is installed.

a. Megahertz measurement may be inaccurate if other programs were busy during last

analysis.

b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.

c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.

d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.



Computer Profile Summary

Computer Name: Main (in WORKGROUP)

Profile Date: Monday, June 23, 2003 15:36:26

Advisor Version: 6.0c

Windows Logon: admin

Operating System

Windows 95 B (OSR2) (build 4.0.1111)

Processor ^a

200 megahertz Intel Pentium w/MMX
32 kilobyte primary memory cache
512 kilobyte secondary memory cache

Drives

1.75 Gigabytes Usable Hard Drive
Capacity
895 Megabytes Hard Drive Free Space

SONY CD-ROM CDU611
Generic floppy disk drive (3.5")
HP HP35480A [Tape drive]

FUJITSU MPA3017ATU [Hard drive]
(1.75 GB) -- drive 0

Logins

No details available

System Model

Viglen Limited

Main Circuit Board ^b

Board: Viglen Limited Vig48M
Bus Clock: 66 megahertz
BIOS: Award Software International,
Inc. 4.51 PG 10/28/97

Memory Modules ^{c,d}

80 Megabytes Installed Memory

Slot '0' has 32 MB
Slot '1' has 32 MB
Slot '2' has 8 MB
Slot '3' has 8 MB
Slot '4' is Empty
Slot '5' is Empty

Local Drive Volumes

c: (on drive 0)	1.75 GB	895 MB free
-----------------	------------	----------------

Network Drives

**mounted by admin at 06/23/03
15:36:20**

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	507 MB	333 MB free
z: \\smrcp\sys	507 MB	333 MB free

Installed Microsoft Hotfixes

UPD001 (OLE 32 update)
 UPD002 (Shell update)

Printers

Canon BJC-610 on LPT1:
Canon Bubble-Jet BJC-600 on LPT1:

- UPD003 (Common dialog update for Windows 3.1 print drivers)
- UPD004 (File and printer sharing update for Microsoft Networks)
- UPD005 (File and printer sharing update for Netware Networks)
- UPD006 (Vredir update for Samba UNIX servers)
- UPD007 (Enhanced password cache security update)
- UPD008 (System Agent update)
- UPD010 (Printer Port update)
- UPD980323B1 (Windows 95 Year 2000 Update)

HP DeskJet 690C Series v11.0 on LPT1:
 HP LaserJet Series II on LPT1:
 MS Publisher Color Printer on FILE:
 MS Publisher Imagesetter on FILE:

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
 Primary IDE controller (single fifo)
 Secondary IDE controller (single fifo)
 Standard Dual PCI IDE Controller
 Standard IDE/ESDI Hard Disk Controller

Bus Adapters

Symbios Logic 875XS|D PCI SCSI Adapter

Communications

Standard 28800 bps Modem
 D-Link DE-528 Ethernet PCI Adapter
 Network Card MAC Address:
 00:50:BA:BB:2B:41
 Network IP Address: 172.19.44.29 / 24

Display

Cirrus Logic 5446 PCI [Display adapter]
 Super VGA 800x600 [Monitor]

Multimedia

None detected

Other Devices

Standard 101/102-Key or Microsoft Natural Keyboard
 Standard PS/2 Port Mouse
 Summit Accelerator

Software Licenses

Microsoft - MS Office 97 Professional
 00510-270-8298942-53784

Microsoft - 80672-045-0104394-
Publisher 98 CD 93279
Microsoft - 13298-OEM-0032072-
Windows 95 B 11094
(OSR2)

Software Versions

Adobe Acrobat Version 4.0.000 <u>*</u>	Microsoft PowerPoint for Windows
Analyst <u>*</u>	Version 8.0b <u>*</u>
Apple Computer, Inc. - QuickTime	Microsoft Registration Wizard Version 2.0
QuickTime 4.0.1 <u>*</u>	<u>*</u>
Banner Blue Software Incorporated -	Microsoft® Access Version 8.0.5903 <u>*</u>
Microsoft Organization Chart Version	Microsoft® Find Fast Version 8.0 <u>*</u>
2,0,0,1016 <u>*</u>	Microsoft® NetMeeting(TM) Version 1.0.
Belarc, Inc. - BelManage Client Version	<u>*</u>
6.0c <u>*</u>	Microsoft® Publisher for Windows® 95
DK Multimedia - Human Body Explorer	Version 5.0 Version 5.0 <u>*</u>
Version 1.00.0193 <u>*</u>	Microsoft® Schedule+ for Windows
InstallShield unInstaller Version	95(TM) Version 7.5 <u>*</u>
2.20.926.0 <u>*</u>	Microsoft® Windows Printing System
LapLink Gold Version 03,10,35,00 <u>*</u>	Version 1.80.04.208 <u>*</u>
LapLink.com, Inc. - Scheduler Version	Microsoft® Word for Windows® 97
03,01,33,00 <u>*</u>	Version 8.0b <u>*</u>
Logotron Ltd - Junior PinPoint Version	MindVision Software - Installer VISE
2.0.12.01 <u>*</u>	Version 2.2 <u>*</u>
Maths Explorer <u>*</u>	NDPS <u>*</u>
Microsoft Corporation - ActiveMovie	Novell Client Login for 32-bit Windows
Version 4.00.96.0729 <u>*</u>	Version 1.00.07 <u>*</u>
Microsoft Corporation - Clip Gallery 4.0	Novell wm95 Version 1, 0, 0, 1 <u>*</u>
for Windows Version 4.0 <u>*</u>	Progressive Networks, Inc. - RealAudio®
Microsoft Corporation - Windows Internet	Player (32-bit) Version 2.1 Version 2.1.1.9
Explore Version 4.70.1155 <u>*</u>	<u>*</u>
Microsoft Corporation - Windows	QBWIN.EXE <u>*</u>
Telephony Version 1.0.501 <u>*</u>	QuickTime Updater <u>*</u>
Microsoft Excel Version 8.0e <u>*</u>	Textease <u>*</u>
Microsoft Office Binder Version 8.0.3501	The Microsoft® Network Version 1.60.0 <u>*</u>
<u>*</u>	Wang Laboratories, Inc. - Imaging for
Microsoft Office Version 8.0 <u>*</u>	Windows 95 Version 1.01.20136 <u>*</u>
Microsoft Open Database Connectivity	
Version 3.0.2822 <u>*</u>	
Microsoft Outlook Version 8.04 <u>*</u>	

Computer Profile Summary

Computer Name: Netvista01 (in WORKGROUP)

Profile Date: Monday, June 23, 2003 14:59:45

Advisor Version: 6.0c

Windows Logon: admin

Operating System

Windows 98 (build 4.10.1998)

Processor ^a

1000 megahertz Intel Pentium III
32 kilobyte primary memory cache
256 kilobyte secondary memory cache

Drives

20.39 Gigabytes Usable Hard Drive
Capacity
19.09 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
LITEON CD-ROM LTN486S
Generic floppy disk drive (3.5")

Generic IDE hard disk drive (20.39 GB)
-- drive 0

Logins

No details available

Installed Microsoft Hotfixes

No details available

[Click here](#) to see all available security Hotfixes.

Marks a HotFix that verifies correctly

System Model

IBM 6269VBG
System Serial Number: 5537Y7B

Main Circuit Board ^b

Board: IBM 6269VBG
Serial Number: P367LYO7JBV
Bus Clock: 133 megahertz
BIOS: IBM PTKT19AUS 03/05/2001

Memory Modules ^{c,d}

128 Megabytes Installed Memory

Slot 'DIMM 0' has 128 MB
Slot 'DIMM 1' is Empty

Local Drive Volumes

c: (on drive 0)	12.24 GB	10.97 GB free
d: (on drive 0)	8.14 GB	8.12 GB free

Network Drives

mounted by admin at 06/23/03
14:59:36

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Printers

Epson Stylus Pro ESC/P 2 on \\pc01\epson
HP Color LaserJet 4550 PCL 6 on \\Smrcp\HP_COLOUR
HP LaserJet on LPT1:

Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
An unmarked HotFix lacks the data to allow verification

2100 Series
PCL 6
HP LaserJet
2100 Series on 172.19.44.150
PCL 6
SMART Print
Capture Driver on FILE1:

Controllers

Standard Floppy Disk Controller
Intel(r) 82801AA Ultra ATA Controller
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)

Bus Adapters

Intel(r) 82801AA USB Universal Host
Controller

Communications

Accton EN1207D Series PCI Fast
Ethernet Adapter
Network Card MAC Address:
00:10:B5:DC:8F:D8
Network IP Address: 172.19.44.14 / 24

Display

Intel(R) 82810E Graphics Controller
[Display adapter]
(Unknown Monitor)

Multimedia

Gameport Joystick (no joystick
connected)
MPU-401 Compatible
SoundMAX Integrated Digital Audio

Other Devices

Avantis CD-ROM Controller
Standard 101/102-Key or Microsoft
Natural Keyboard
USB Root Hub

Software Licenses

Microsoft - 50071-439-9501472-
Internet Explorer04939
Microsoft - MS 00510-270-9122777-
Office 97 20875
Professional 16301-OEM-0070142-
Microsoft - 49590 (Key: B8C7H-
Windows 98 3P6H7-RFMJQ-76T7Y-
YKKT)

Software Versions

Adobe Acrobat Version 3.0.000_*
Apple Computer, Inc. - QuickTime for
Windows Version 2.1.2.59_*
Apple Computer, Inc. MoviePlayer
Application Version 3, 0, 0, 1_*
Apple Computer, Inc. PictureViewer
Application Version 3, 0, 0, 1_*
Avantis CD Installation Wizard Version
3.2_*
Avantis CDsPlayer Version 3.2_*
Avantis Ltd - CDserve Monitor
Application Version 3.23_*
Avantis Ltd. - CDserve Version 3.2_*
Banner Blue Software Incorporated -
Microsoft Organization Chart Version
2,0,0,1016_*
Belarc, Inc. - BelManage Client Version
6.0c_*
Crick Software Ltd - CLICKER 3 Version
3.06.0007_*
DataTree Application Version 1, 0, 0, 1_*
Microsoft Corporation - Windows
Telephony Version 1.0.501_*
Microsoft Excel Version 8.0e_*
Microsoft imgstart Version 1, 0, 0, 1_*
Microsoft Map Version 8.00.00.01621_*
Microsoft Office Binder Version 8.0.3501
_*
Microsoft Office Version 8.0_*
Microsoft Outlook Version 8.04_*
Microsoft Photo Editor Version 3.0_*
Microsoft PowerPoint for Windows
Version 8.0b_*
Microsoft Windows Scripting Host
Version 5.0.531.7_*
Microsoft® Access Version 8.0.5903_*
Microsoft® Find Fast Version 8.0_*
Microsoft® FrontPage(TM) Version
2.0.2.1131_*
Microsoft® Internet Services Version
6.1.33.0_*
Microsoft® NetMeeting® Version 2.11_*

DeMartini Consulting - AutoLaunch
Version 1.2RC2*
Eastman Software, Inc., A Kodak Business
- Imaging for Windows® Version
1.01.1311*
Fisher-Marriott Software - STARSPEL
Version 1.00.0056*
Garden!*
Genigraphics®, An In Focus Systems®
Company - GraphicsLink(TM) for
Windows Version 8.0*
Hewlett Packard Add JetDirect Printer
Version 1, 0, 0, 1*
Hewlett-Packard Company - HP
FontSmart v2.5*
HP LaserJet 2100 uninstaller*
Impac Resources Ltd. - RM Music
Explorer*
InstallShield Deinstaller Version
2.20.914.0*
InstallShield unInstaller Version
2.20.924.0*
LAUNCHER Application Version 1, 0, 0,
1*
Logotron - PicturePoint Version 1.0.001*
Logotron Ltd - Junior PinPoint Version
2.0.12.01*
Macromedia Director Version 6.0.2*
Macromedia Director Version 6.5*
Macromedia, Inc. - Flash 4.0 Version
4,0,7,0*
Maths Explorer*
Microsoft Corporation - Clip Gallery 3.0
for Windows Version 3.0*
Microsoft Corporation - DirectShow
Version 6.01.05.0130*
Microsoft Corporation - Microsoft Internet
Explorer Version 5.00.2314.1000*
Microsoft® Schedule+ for Windows
95(TM) Version 7.5*
Microsoft® Word for Windows® 97
Version 8.0b*
MP Express Player Startup*
MP Express Startup*
NDPS*
Newman College - Bounce Version 1.00*
Novell Client Login for 32-bit Windows
Version 1.00.07*
Novell wm95 Version 1, 0, 0, 1*
Project Launch*
RoamerWorld*
Seagate Software, Inc. - Backup*
Sherston Software Playbook*
Silica Software Systems - Dazzle
Application Version 1, 4, 1, 0*
SMART Board Software Version 1, 0, 1,
21*
SMART Board Software Version 2.4.1.21
*
SMART Board Software Version 7.0.1.21
*
Stage 2*
Textease*

Computer Profile Summary

Computer Name:Netvista05 (in WORKGROUP)

Profile Date:Monday, June 23, 2003 15:18:29

Advisor Version:6.0c

Windows Logon:admin

Operating System

Windows 98 (build 4.10.1998)

Processor ^a

1000 megahertz Intel Pentium III
32 kilobyte primary memory cache
256 kilobyte secondary memory cache

Drives

20.39 Gigabytes Usable Hard Drive Capacity
19.15 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
LITEON CD-ROM LTN486S
Generic floppy disk drive (3.5")

Generic IDE hard disk drive (20.39 GB)
-- drive 0

Logins

No details available

System Model

IBM 6269VBG
System Serial Number: 5537Y8B

Main Circuit Board ^b

Board: IBM 6269VBG
Serial Number: P367LYU8XBE
Bus Clock: 133 megahertz
BIOS: IBM PTKT19AUS 03/05/2001

Memory Modules ^{c,d}

128 Megabytes Installed Memory

Slot 'DIMM 0' has 128 MB
Slot 'DIMM 1' is Empty

Local Drive Volumes

c: (on drive 0)	12.24 GB	11.03 GB free
d: (on drive 0)	8.14 GB	8.12 GB free

Network Drives

mounted by admin at 06/23/03 15:18:19

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Installed Microsoft Hotfixes

No details available

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
Intel(r) 82801AA Ultra ATA Controller
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)

Printers

Epson Stylus Pro ESC/P 2 on \\pc01\epson
HP Color LaserJet 4550 PCL 6 on \\Smrcp\HP_COLOUR
HP LaserJet 2100 Series PCL 6 on LPT1:
HP LaserJet 2100 Series PCL 6 on 172.19.44.150

Display

Intel(R) 82810E Graphics Controller [Display adapter]
Sony CPD-E220E [Monitor] (16.1"vis, s/n 4513717, September 2000)

Bus Adapters

Intel(r) 82801AA USB Universal Host Controller

Multimedia

Gameport Joystick (no joystick connected)
MPU-401 Compatible
SoundMAX Integrated Digital Audio

Communications

Accton EN1207D Series PCI Fast Ethernet Adapter
Network Card MAC Address: 00:10:B5:DC:90:85
Network IP Address: 172.19.44.25 / 24

Other Devices

Avantis CD-ROM Controller
Standard 101/102-Key or Microsoft Natural Keyboard
USB Root Hub

Software Licenses

Microsoft - 50071-439-9501472-Internet Explorer04939
Microsoft - MS Office 97 Professional 00510-270-9122777-20875
16301-OEM-0070142-
Microsoft - Windows 98 49590 (Key: B8C7H-3P6H7-RFMJQ-76T7Y-YKKT)

Software Versions

Adobe Acrobat Version 3.0.000*
Apple Computer, Inc. - QuickTime for Windows Version 2.1.2.59*
Apple Computer, Inc. MoviePlayer Application Version 3, 0, 0, 1*
Apple Computer, Inc. PictureViewer Application Version 3, 0, 0, 1*
Avantis CD Installation Wizard Version 3.2*
Avantis CD'sPlayer Version 3.2*
Avantis Ltd - CDserve Monitor Application Version 3.23*
Avantis Ltd. - CDserve Version 3.2*
Banner Blue Software Incorporated - Microsoft Organization Chart Version 2,0,0,1016*
Belarc, Inc. - BelManage Client Version 6.0c*
Crick Software Ltd - CLICKER 3 Version 3.06.0007*
DataTree Application Version 1, 0, 0, 1*
DeMartini Consulting - AutoLaunch Version 1.2RC2*
Eastman Software, Inc., A Kodak Business - Imaging for Windows® Version 1.01.1311*
Fisher-Marriott Software - STARSPEL Version 1.00.0056*
Garden!*
Geniographics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0*
Hewlett Packard Add JetDirect Printer Version 1, 0, 0, 1*
Microsoft Corporation - Windows Telephony Version 1.0.501*
Microsoft Excel Version 8.0e*
Microsoft imgstart Version 1, 0, 0, 1*
Microsoft Map Version 8.00.00.01621*
Microsoft Office Binder Version 8.0.3501*
Microsoft Office Version 8.0*
Microsoft Outlook Version 8.04*
Microsoft Photo Editor Version 3.0*
Microsoft PowerPoint for Windows Version 8.0b*
Microsoft Windows Scripting Host Version 5.0.531.7*
Microsoft® Access Version 8.0.5903*
Microsoft® Find Fast Version 8.0*
Microsoft® FrontPage(TM) Version 2.0.2.1131*
Microsoft® Internet Services Version 6.1.33.0*
Microsoft® NetMeeting® Version 2.11*
Microsoft® Schedule+ for Windows 95(TM) Version 7.5*
Microsoft® Word for Windows® 97 Version 8.0b*
MP Express Player Startup*
MP Express Startup*
NDPS*
Newman College - Bounce Version 1.00*
Novell Client Login for 32-bit Windows Version 1.00.07*
Novell wm95 Version 1, 0, 0, 1*
Project Launch*
RoamerWorld*

Hewlett-Packard Company - HP
FontSmart v2.5*
HP LaserJet 2100 uninstaller*
Impac Resources Ltd. - RM Music
Explorer*
InstallShield Deinstaller Version
2.20.914.0*
InstallShield unInstaller Version
2.20.924.0*
LAUNCHER Application Version 1, 0, 0,
1*
Logotron - PicturePoint Version 1.0.001*
Logotron Ltd - Junior PinPoint Version
2.0.12.01*
Macromedia Director Version 6.0.2*
Macromedia Director Version 6.5*
Macromedia, Inc. - Flash 4.0 Version
4,0,7,0*
Maths Explorer*
Microsoft Corporation - Clip Gallery 3.0
for Windows Version 3.0*
Microsoft Corporation - DirectShow
Version 6.01.05.0130*
Microsoft Corporation - Microsoft Internet
Explorer Version 5.00.2314.1000*

Seagate Software, Inc. - Backup*
Sherston Software Playbook*
Silca Software Systems - DazzlePlus
Application Version 2, 0, 0, 0*
Silca Software Systems - Dazzle
Application Version 1, 4, 1, 0*
Silca Software Systems - Project Presenter
Version 1, 5, 3, 0*
Stage 2*
Textease*

Computer Profile Summary

*Computer Name:*Pbn computer (in WORKGROUP)

*Profile Date:*Monday, June 23, 2003 15:43:12

*Advisor Version:*6.0c

*Windows Logon:*admin

Operating System

Windows 98 (build 4.10.1998)

Processor ^a

225 megahertz Cyrix MII
64 kilobyte primary memory cache
512 kilobyte secondary memory cache

Drives

3.23 Gigabytes Usable Hard Drive Capacity
1.70 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
GoldStar CD-ROM CRD-8322B
Generic floppy disk drive (3.5")

Generic IDE hard disk drive (3.23 GB) -- drive 0

Logins

admin
ch
de
gh
kertonmi
year4

System Model

Packard Bell NEC Packard Bell
Computer P070001901
System Serial Number: C417100256

Main Circuit Board ^b

Board: SiS-5598-W877F
Bus Clock: 75 megahertz
BIOS: Award Software International, Inc. 4.51 PG 10/23/98

Memory Modules ^{c,d}

28 Megabytes Installed Memory

Slot '0' has 32 MB
Slot '1' is Empty

Local Drive Volumes

c: (on drive 0)	3.23 GB	1.70 GB free
-----------------	---------	--------------

Network Drives

mounted by admin at 06/23/03 15:42:43

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Installed Microsoft Hotfixes

Internet Explorer

Printers

CAPTURE FAX BVRP on FAX:

SP1 (SPI)

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)
SiS 5513 Dual PCI IDE Controller

Bus Adapters

SiS 7001 PCI to USB Open Host Controller

Communications

MDP3858-E Modem #2
ND01X Ethernet/Fast Ethernet PCI Bus Adapter
Network Card MAC Address:
00:10:A7:08:A7:AC
Network IP Address: 172.19.44.28 / 24

Capture fax BVRP Extended on FAX:
Epson Stylus COLOR ESC/P on LPT1:
2
HP DeskJet 690C on LPT1:
HP LaserJet Series II on LPT1:
OLICHRROME Olivetti JP192 on LPT1:

Display

SiS 5597/5598 [Display adapter]
Packard Bell PBN 1015 [Monitor]
(13.2"vis, s/n LEMN84702305,
November 1998)

Multimedia

ES1869 Control Interface
ES1869 Plug and Play AudioDrive
Gameport Joystick (no joystick connected)

Other Devices

Avantis CD-ROM Controller
MDP3858 PCI Modem Enumerator
Standard 101/102-Key or Microsoft
Natural Keyboard
PS2 (PS/2) [Mouse]
USB Root Hub

Software Licenses

Microsoft - 68480-OEM-1208613-
Money 98 23458
Microsoft - MS 53491-270-5631501-
Office 97 31658
Professional 06199-OEM-0073614-
Microsoft - 78965 (Key: QCBVY-
Windows 98 BQ8QR-XBXHX-
83TM7-MRM9D)
Microsoft - 00000-OEM-0000000-
Word for 00000
Windows
Microsoft - 11195-OEM-0310021-
Works 4.5 81354

Software Versions

Adiboo 2 Environment *
Adobe Acrobat Version 3.0.000 *
Apple Computer, Inc. - QuickTime
QuickTime 4.0.1 *
Avantis CD Installation Wizard Version
3.2 *
Avantis CDsPlayer Version 3.2 *
Avantis Ltd - CDserve Monitor
Application Version 3.23 *
Avantis Ltd. - CDserve Version 3.2 *
Banner Blue Software Incorporated -
Microsoft Organization Chart Version
Microsoft Photo Editor Version 3.0 *
Microsoft PowerPoint for Windows
Version 8.0 *
Microsoft Windows Scripting Host
Version 5.0.531.7 *
Microsoft Works for Windows Version
4.00.03.458 *
Microsoft® Plus! for Windows® 95
Version 4.40.500 *
Microsoft® Access Version 8.0.4122 *
Microsoft® Chat Version 2.1 *
Microsoft® Find Fast Version 8.0 *

2,0,0,1016*
 Belarc, Inc. - BelManage Client Version 6.0c*
 Bus Stop Utility - Human Body*
 BVRP Software - PhoneTools Version 2.10*
 CompuServe for Windows Version 3.0*
 Configure Media Player*
 Cyber Patrol Installation*
 DataTree Application Version 1, 0, 0, 1*
 DK Multimedia - Human Body Explorer Version 1.00.0193*
 DK Multimedia - I Love Maths! Version 1.0.0.0*
 DK Multimedia - My First Amazing History Explorer Sampler Version 8.01.001-*
 Eastman Software, Inc., A Kodak Business - Imaging for Windows® Version 1.01.1311*
 Event Reminder*
 Fisher-Marriott Software - STARSPEL Version 1.00.0056*
 Genigraphics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0*
 GOTO Software - WebEarly 98 Version 2.01*
 InstallShield unInstaller Version 2.20.926.0*
 JP192 Uninstall program*
 LAUNCHER Application Version 1, 0, 0, 1*
 Logitech Inc. - MouseWare Version 8.02*
 Logotron Ltd - Junior PinPoint Version 2.0.12.01*
 Lotus ScreenCam Version 3, 0, 0, 6*
 Macromedia Director Version 5.0*
 Macromedia Director Version 6.0.2*
 Macromedia Director Version 6.5*
 Macromedia Director Version 7.0.2*
 Maths Explorer*
 Media Station Inc. - The Lion King LKASBv2.0/GB*
 Micrografx ABC Graphics Suite Version 6.00.001*
 Micrografx Windows Draw Version 4, 0, 0, 1*
 Micrografx, Inc. Photo Magic Version 4.00a*
 Microsoft Corporation - Clip Gallery 3.0 for Windows Version 3.0*
 Microsoft Corporation - Windows Internet Explorer Version 4.72.3110.0*
 Microsoft Corporation - Windows Telephony Version 1.0.501*
 Microsoft Encarta Version 6.00.43.00013*
 Microsoft Excel Version 8.0a*
 Microsoft Kids Catalog Version 2.00*
 Microsoft Map Version 8.00.00.01621*
 Microsoft® FrontPage(TM) Version 2.0.2.1118*
 Microsoft® Internet Services Version 6.1.33.0*
 Microsoft® NetMeeting(TM) Version 2.1*
 Microsoft® NetShow Version 2.0.0.912*
 Microsoft® Schedule+ for Windows 95(TM) Version 7.5*
 Microsoft® Word for Windows® 97 Version 8.0*
 MindVision Software - Installer VISE Version 2.2*
 MNYIMPRT.EXE*
 MP Express Player Startup*
 MP Express Startup*
 NDPS*
 Netscape Communications NSConf32 Version 4, 0, 0, 1*
 Netscape Mail Notification*
 NETSCAPE Version 4.04*
 Novell Client Login for 32-bit Windows Version 1.00.07*
 Novell wm95 Version 1, 0, 0, 1*
 Olivetti - OLICHROME (TM) Version 3.1.1*
 Packard Bell Navigator Version 1.0.7.1*
 Packard Bell NEC - PB SoftBar Version 2.1*
 Packard Bell Nec, Inc. - ClickMe Version 3.2.0.0*
 Packard Bell Tutorials Version 1.0.0.0*
 PB NETp@ss & Registration*
 Peak Interactive EMail 100431.3430 @compuserve.com - Mathematics Version 1.00*
 PhotoStudio Lite*
 PhotoStudio Registration*
 PrintMaster Web Site*
 Progressive Networks, Inc. - RealPlayer (32-bit) Version 4.01 Version 4.0.20.155*
 QuickTime Updater*
 Seagate Software, Inc. - Backup Sensing*
 Sherston Software Playbook*
 Symantec Core Technology Version 19.0.0.128*
 Symantec Corporation - Norton AntiVirus Core Technology Version 5.0.0.52*
 Symantec Corporation - Norton AntiVirus Version 5.0.0.48*
 Textease*
 The Logical Journey of the Zoombinis*
 Timing*
 WaterGate Software Inc. - PC-Doctor For Windows 3.0 Version 3.0*
 ZebraSoft, Inc. - Norton Uninstall Deluxe Version 1, 0, 0, 1*
 ZebraSoft, Inc. - SymMon Module Version 1, 0, 0, 1*

Microsoft Money Version 6.00 * Zoombinis Midi Setup *
Microsoft Multimedia Viewer Version ôRA CREATIVE - Le Compteur Internet
2.00 * Européen Version 2.20 Build 0512 *
Microsoft Office Binder Version 8.0.3501
*
Microsoft Office Version 8.0.3512 *
Microsoft Outlook Version 8.0 *
Microsoft Outlook Version 8.02 *

- * Click to see where software is installed.
- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
 - b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
 - c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
 - d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.
Legal notice. U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name:Pc01 (in WORKGROUP)

Profile Date:Monday, June 23, 2003 15:14:03

Advisor Version:6.0c

Windows Logon:admin

Operating System

Windows 95 B (OSR2) (build 4.3.1212)

Processor ^a

400 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Drives

4.20 Gigabytes Usable Hard Drive Capacity
2.65 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
TEAC CD-540E [CD-ROM drive]
Generic floppy disk drive (3.5")

WDC AC14300R [Hard drive] (4.31 GB) -- drive 0

Logins

No details available

System Model

Compaq Deskpro EP/SB Series
System Serial Number: 8911CL929185
Asset Tag: 8911CL929185
Chassis Serial Number: 8911CL929185

Main Circuit Board ^b

Board: Compaq 046Ch
Serial Number: 8911CL929185
Bus Clock: 66 megahertz
BIOS: Compaq 686T1 12/09/98

Memory Modules ^{c,d}

32 Megabytes Installed Memory

Slot 'DIMM #1:J1' has 32 MB
Slot 'DIMM #2:J2' is Empty

Local Drive Volumes

c: (on drive 0)	2.11 GB	555 MB free
d: (on drive 0)	2.10 GB	2.09 GB free

Network Drives

mounted by admin at 06/23/03
15:13:42

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Installed Microsoft Hotfixes

UPD001 (OLE 32 update)

Printers

EPSON Stylus COLOR 640 on LPT1:

- UPD002 (Shell update)
- UPD003 (Common dialog update for Windows 3.1 print drivers)
- UPD004 (File and printer sharing update for Microsoft Networks)
- UPD005 (File and printer sharing update for Netware Networks)
- UPD006 (Vredir update for Samba UNIX servers)
- UPD007 (Enhanced password cache security update)
- UPD008 (System Agent update)
- UPD010 (Printer Port update)

HP Color LaserJet 4550 PCL 6 on \\Smrcp_tree\Hp Colour.SMRCP
 HP DeskJet 560C Printer on LPT1:
 HP LaserJet 2100 Series PCL 5e on 172.19.44.150

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
 Intel 82371AB/EB PCI Bus Master IDE Controller
 Primary IDE controller (dual fifo)
 Secondary IDE controller (dual fifo)

Bus Adapters

Intel 82371AB/EB PCI to USB
 Universal Host Controller

Communications

D-Link DE220 ISA PnP LAN adapter
 Network Card MAC Address:
 00:80:C8:D8:BF:13
 Network IP Address: 172.19.44.22 / 24

Display

NVIDIA RIVA TNT2 Model 64/Model 64 Pro [Display adapter]
 COMPAQ S700 [Monitor] (16.3"vis, s/n 903CD61TN389, January 1999)

Multimedia

Creative Gameport Joystick
 Creative Sound Blaster 16 PCI
 Sound Blaster 16 PCI Legacy Device

Other Devices

Avantis CD-ROM Controller
 Standard 101/102-Key or Microsoft Natural Keyboard
 Standard PS/2 Port Mouse
 USB Root Hub

Software Licenses

Microsoft - 71929-OEM-2000014-Internet Explorer12345
 Microsoft - MS 53233-270-4527505-Office 97 57808
 Microsoft - 32498-OEM-0039225-Windows 95 B 45893 (OSR2)

Software Versions

Adobe Acrobat Version 3.0.000*
 Apple Computer, Inc. - QuickTime for Windows Version 2.1.2.59*
 Apple Computer, Inc. MoviePlayer

Microsoft Backup Version 4.0.952*
 Microsoft Corporation - Clip Gallery 3.0 for Windows Version 3.0*
 Microsoft Corporation - DirectShow

Application Version 3, 0, 0, 1 [*](#)
Apple Computer, Inc. PictureViewer
Application Version 3, 0, 0, 1 [*](#)
Asymetrix Corp. - Multimedia Toolbook
Version 3.0a [*](#)
Avantis CD Installation Wizard Version
3.2 [*](#)
Avantis CDsPlayer Version 3.2 [*](#)
Avantis Ltd - CDserve Monitor
Application Version 3.23 [*](#)
Avantis Ltd. - CDserve Version 3.2 [*](#)
Banner Blue Software Incorporated -
Microsoft Organization Chart Version
2,0,0,1016 [*](#)
Belarc, Inc. - BelManage Client Version
6.0c [*](#)
Brain Builder [*](#)
Crick Software Ltd - CLICKER 3 Version
3.06.0007 [*](#)
DataTree Application Version 1, 0, 0, 1 [*](#)
DeMartini Consulting - AutoLaunch
Version 1.2RC2 [*](#)
Dictionary Editor [*](#)
Garden! [*](#)
Genigraphics®, An In Focus Systems®
Company - GraphicsLink(TM) for
Windows Version 8.0 [*](#)
Hewlett Packard Add JetDirect Printer
Version 1, 0, 0, 1 [*](#)
Hewlett-Packard Company - HP
FontSmart v2.5 [*](#)
Hewlett-Packard Company - HP LaserJet
2100 Configuration Utility Application
Version 1, 0, 2, 0 [*](#)
HP LaserJet 2100 uninstaller [*](#)
InstallShield Deinstaller Version
2.20.914.0 [*](#)
InstallShield unInstaller Version
2.20.924.0 [*](#)
Intel DMI Explorer Version 1.11 [*](#)
Johan Savås - ZipCentral Version 3.00 [*](#)
LAUNCHER Application Version 1, 0, 0,
1 [*](#)
Logotron - PicturePoint Version 1.0.001 [*](#)
Logotron Ltd - Junior PinPoint Version
2.0.12.01 [*](#)
Macromedia Director Version 6.0.2 [*](#)
Macromedia Director Version 6.5 [*](#)
Macromedia, Inc. - Flash 4.0 Version
4,0,7,0 [*](#)
Maths Explorer [*](#)
Matrox Graphics Inc. Matrox Control
Center Version 4.10.007 [*](#)
Matrox Graphics Inc. mgadnav Version
4.10.007 [*](#)
Matrox Graphics Inc. mgaqdesk Version
4.10.007 [*](#)
Matrox PowerDesk Version 4.10.007 [*](#)
Megapaint [*](#)
Version 6.01.05.0130 [*](#)
Microsoft Corporation - Microsoft Internet
Explorer Version 5.00.2014.200 [*](#)
Microsoft Corporation - Windows
Telephony Version 4.10.2000 [*](#)
Microsoft Excel Version 8.0e [*](#)
Microsoft Map Version 8.00.00.01621 [*](#)
Microsoft Office Binder Version 8.0.3501
[*](#)
Microsoft Office Version 8.0 [*](#)
Microsoft Outlook Version 8.04 [*](#)
Microsoft Photo Editor Version 3.0 [*](#)
Microsoft PowerPoint for Windows
Version 8.0b [*](#)
Microsoft Registration Wizard Version 2.0
[*](#)
Microsoft Windows Scripting Host
Version 5.0.531.7 [*](#)
Microsoft® Schedule+ for Windows
95(TM) Version 7.5 [*](#)
Microsoft® Word for Windows® 97
Version 8.0b [*](#)
NDPS [*](#)
Newman College - Bounce Version 1.00 [*](#)
Novell Client Login for 32-bit Windows
Version 1.00.07 [*](#)
Progressive Networks, Inc. - RealAudio®
Player (32-bit) Version 2.1 Version 2.1.1.9
[*](#)
Resarch Machine plc - Colour Options
Version 1, 1, 0, 0 [*](#)
Research Machines plc - Talking First
Word Version 1.01.0019 [*](#)
Roger Wagner Publishing, Inc. -
HyperStudio Version 3.2 [*](#)
RWORLD.EXE [*](#)
Sherston Software Playbook [*](#)
Silica Software Systems - Dazzle
Application Version 1, 4, 1, 0 [*](#)
Sonnetech Ltd. - Colorific for Windows 95
Version 4.10.007 [*](#)
Superdisk [*](#)
SuperLogo [*](#)
Symantec Core Technology Version
20.0.0.197 [*](#)
Symantec Corporation - Norton AntiVirus
Core Technology Version 5.3.0.168 [*](#)
Symantec Corporation - Norton AntiVirus
Version 5.3.2.50 [*](#)
Textease [*](#)
The Microsoft® Network Version 1.60.0 [*](#)
Tips and Tour [*](#)
Wang Laboratories, Inc. - Imaging for
Windows 95 Version 1.01.20136 [*](#)
WinZip Version 8.0 (3105) [*](#)

* Click to see where software is installed.

- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.

[Legal notice](#). U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name:Pc02 (in WORKGROUP)

Profile Date:Monday, June 23, 2003 15:14:57

Advisor Version:6.0c

Windows Logon:admin

Operating System

Windows 95 B (OSR2) (build 4.3.1212)

Processor ^a

400 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Drives

4.20 Gigabytes Usable Hard Drive Capacity
2.66 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
TEAC CD-540E [CD-ROM drive]
Generic floppy disk drive (3.5")

WDC AC14300R [Hard drive] (4.31 GB) -- drive 0

Logins

No details available

System Model

Compaq Deskpro EP/SB Series
System Serial Number: 8911CL929099
Asset Tag: 8911CL929099
Chassis Serial Number: 8911CL929099

Main Circuit Board ^b

Board: Compaq 046Ch
Serial Number: 8911CL929099
Bus Clock: 66 megahertz
BIOS: Compaq 686T1 12/09/98

Memory Modules ^{c,d}

64 Megabytes Installed Memory

Slot 'DIMM #1:J1' has 32 MB
Slot 'DIMM #2:J2' has 32 MB

Local Drive Volumes

c: (on drive 0)	2.11 GB	590 MB free
d: (on drive 0)	2.10 GB	2.07 GB free

Network Drives

mounted by admin at 06/23/03 15:14:37

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Installed Microsoft Hotfixes

UPD001 (OLE 32 update)

Printers

EPSON Stylus COLOR 640 on \\PC01\Epson

- UPD002 (Shell update)
- UPD003 (Common dialog update for Windows 3.1 print drivers)
- UPD004 (File and printer sharing update for Microsoft Networks)
- UPD005 (File and printer sharing update for Netware Networks)
- UPD006 (Vredir update for Samba UNIX servers)
- UPD007 (Enhanced password cache security update)
- UPD008 (System Agent update)
- UPD010 (Printer Port update)

HP Color LaserJet 4550 PCL 6
 on \\Smrcp_tree\Hp Colour.SMRCP

HP LaserJet 2100 Series PCL 5e
 on 172.19.44.150

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
 Intel 82371AB/EB PCI Bus Master IDE Controller
 Primary IDE controller (dual fifo)
 Secondary IDE controller (dual fifo)

Bus Adapters

Intel 82371AB/EB PCI to USB
 Universal Host Controller

Communications

D-Link DE220 ISA PnP LAN adapter
 Network Card MAC Address:
 00:80:C8:D8:CB:B7
 Network IP Address: 172.19.44.23 / 24

Display

Matrox MGA -G100 AGP [Display adapter]
 COMPAQ S700 [Monitor] (16.3"vis, s/n 903CD61TN673, January 1999)

Multimedia

Creative Gameport Joystick
 Creative Sound Blaster 16 PCI
 Sound Blaster 16 PCI Legacy Device

Other Devices

Avantis CD-ROM Controller
 Standard 101/102-Key or Microsoft Natural Keyboard
 Standard PS/2 Port Mouse
 USB Root Hub

Software Licenses

Microsoft - 71929-OEM-2000014-Internet Explorer12345
 Microsoft - MS 53233-270-4527505-

Office 97 57808
Microsoft - 32498-OEM-0039225-
Windows 95 B 45893
(OSR2)

Software Versions

Adobe Acrobat Version 3.0.000*
Apple Computer, Inc. MoviePlayer
Application Version 3, 0, 0, 1*
Apple Computer, Inc. PictureViewer
Application Version 3, 0, 0, 1*
Avantis CD Installation Wizard Version
3.2*
Avantis CDsPlayer Version 3.2*
Avantis Ltd - CDserve Monitor
Application Version 3.23*
Avantis Ltd. - CDserve Version 3.2*
Banner Blue Software Incorporated -
Microsoft Organization Chart Version
2,0,0,1016*
Belarc, Inc. - BelManage Client Version
6.0c*
Crick Software Ltd - CLICKER 3 Version
3.06.0007*
DataTree Application Version 1, 0, 0, 1*
Dictionary Editor*
GENI Application Version 2, 0, 0, 1*
Genigraphics®, An In Focus Systems®
Company - GraphicsLink(TM) for
Windows Version 8.0*
Hewlett Packard Add JetDirect Printer
Version 1, 0, 0, 1*
InstallShield Deinstaller Version
2.20.914.0*
InstallShield unInstaller Version
2.20.924.0*
Intel DMI Explorer Version 1.11*
LAUNCHER Application Version 1, 0, 0,
1*
Logotron - PicturePoint Version 1.0.001*
Logotron Ltd - Junior PinPoint Version
2.0.12.01*
Macromedia Director Version 6.0.2*
Macromedia Director Version 6.5*
Maths Explorer*
Matrox Graphics Inc. Matrox Control
Center Version 4.10.007*
Matrox Graphics Inc. mgadnav Version
4.10.007*
Matrox Graphics Inc. mgaqdesk Version
4.10.007*
Matrox PowerDesk Version 4.10.007*
Megapaint*
Microsoft Backup Version 4.0.952*
Microsoft Corporation - Clip Gallery 3.0
for Windows Version 3.0*
Microsoft Corporation - DirectShow
Version 6.01.05.0130*
Microsoft Corporation - Microsoft Internet
Explorer Version 5.00.2014.200*
Microsoft Corporation - Windows
Telephony Version 4.10.2000*
Microsoft Excel Version 8.0e*
Microsoft Map Version 8.00.00.01621*
Microsoft Office Binder Version 8.0.3501
*
Microsoft Office Version 8.0*
Microsoft Outlook Version 8.04*
Microsoft Photo Editor Version 3.0*
Microsoft PowerPoint for Windows
Version 8.0b*
Microsoft Registration Wizard Version 2.0
*
Microsoft Windows Scripting Host
Version 5.0.531.7*
Microsoft® Schedule+ for Windows
95(TM) Version 7.5*
Microsoft® Word for Windows® 97
Version 8.0b*
NDPS*
Novell Client Login for 32-bit Windows
Version 1.00.07*
Progressive Networks, Inc. - RealAudio®
Player (32-bit) Version 2.1 Version 2.1.1.9
*
Resarch Machine plc - Colour Options
Version 1, 1, 0, 0*
Research Machines plc - Talking First
Word Version 1.01.0019*
Roger Wagner Publishing, Inc. -
HyperStudio Version 3.2*
RWORLD.EXE*
Silica Software Systems - Dazzle
Application Version 1, 4, 1, 0*
Sonnetch Ltd. - Colorific for Windows 95
Version 4.10.007*
Superdisk*
SuperLogo*
Symantec Core Technology Version
20.0.0.197*
Symantec Corporation - Norton AntiVirus
Core Technology Version 5.3.0.168*
Symantec Corporation - Norton AntiVirus
Version 5.3.2.50*
Textease*
Tips and Tour*
Wang Laboratories, Inc. - Imaging for
Windows 95 Version 1.01.20136*

* Click to see where software is installed.

- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.

Legal notice. U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name:Pc02 (in WORKGROUP)

Profile Date:Monday, June 23, 2003 15:14:57

Advisor Version:6.0c

Windows Logon:admin

Operating System

Windows 95 B (OSR2) (build 4.3.1212)

Processor ^a

400 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Drives

4.20 Gigabytes Usable Hard Drive Capacity
2.66 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
TEAC CD-540E [CD-ROM drive]
Generic floppy disk drive (3.5")

WDC AC14300R [Hard drive] (4.31 GB) -- drive 0

Logins

No details available

System Model

Compaq Deskpro EP/SB Series
System Serial Number: 8911CL929099
Asset Tag: 8911CL929099
Chassis Serial Number: 8911CL929099

Main Circuit Board ^b

Board: Compaq 046Ch
Serial Number: 8911CL929099
Bus Clock: 66 megahertz
BIOS: Compaq 686T1 12/09/98

Memory Modules ^{c,d}

64 Megabytes Installed Memory

Slot 'DIMM #1:J1' has 32 MB
Slot 'DIMM #2:J2' has 32 MB

Local Drive Volumes

c: (on drive 0)	2.11 GB	590 MB free
d: (on drive 0)	2.10 GB	2.07 GB free

Network Drives

mounted by admin at 06/23/03 15:14:37

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Installed Microsoft Hotfixes

UPD001 (OLE 32 update)

Printers

EPSON Stylus COLOR 640 on \\PC01\Epson

- UPD002 (Shell update)
- UPD003 (Common dialog update for Windows 3.1 print drivers)
- UPD004 (File and printer sharing update for Microsoft Networks)
- UPD005 (File and printer sharing update for Netware Networks)
- UPD006 (Vredir update for Samba UNIX servers)
- UPD007 (Enhanced password cache security update)
- UPD008 (System Agent update)
- UPD010 (Printer Port update)

HP Color LaserJet 4550 PCL 6
 on \\Smrcp_tree\Hp Colour.SMRCP

HP LaserJet 2100 Series PCL 5e
 on 172.19.44.150

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers	Display
Standard Floppy Disk Controller Intel 82371AB/EB PCI Bus Master IDE Controller Primary IDE controller (dual fifo) Secondary IDE controller (dual fifo)	Matrox MGA -G100 AGP [Display adapter] COMPAQ S700 [Monitor] (16.3"vis, s/n 903CD61TN673, January 1999)
Bus Adapters	Multimedia
Intel 82371AB/EB PCI to USB Universal Host Controller	Creative Gameport Joystick Creative Sound Blaster 16 PCI Sound Blaster 16 PCI Legacy Device
Communications	Other Devices
D-Link DE220 ISA PnP LAN adapter Network Card MAC Address: 00:80:C8:D8:CB:B7 Network IP Address: 172.19.44.23 / 24	Avantis CD-ROM Controller Standard 101/102-Key or Microsoft Natural Keyboard Standard PS/2 Port Mouse USB Root Hub
Software Licenses	
Microsoft - 71929-OEM-2000014-Internet Explorer12345 Microsoft - MS 53233-270-4527505-Office 97 57808 Microsoft - 32498-OEM-0039225-Windows 95 B 45893 (OSR2)	

Software Versions	
Adobe Acrobat Version 3.0.000*	Microsoft Corporation - DirectShow Version 6.01.05.0130*
Apple Computer, Inc. MoviePlayer Application Version 3, 0, 0, 1*	Microsoft Corporation - Microsoft Internet Explorer Version 5.00.2014.200*
Apple Computer, Inc. PictureViewer	

Application Version 3, 0, 0, 1 *
 Avantis CD Installation Wizard Version 3.2 *
 Avantis CDsPlayer Version 3.2 *
 Avantis Ltd - CDserve Monitor Application Version 3.23 *
 Avantis Ltd. - CDserve Version 3.2 *
 Banner Blue Software Incorporated - Microsoft Organization Chart Version 2,0,0,1016 *
 Belarc, Inc. - BelManage Client Version 6.0c *
 Crick Software Ltd - CLICKER 3 Version 3.06.0007 *
 DataTree Application Version 1, 0, 0, 1 *
 Dictionary Editor *
 GENI Application Version 2, 0, 0, 1 *
 GeniGraphics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0 *
 Hewlett Packard Add JetDirect Printer Version 1, 0, 0, 1 *
 InstallShield Deinstaller Version 2.20.914.0 *
 InstallShield unInstaller Version 2.20.924.0 *
 Intel DMI Explorer Version 1.11 *
 LAUNCHER Application Version 1, 0, 0, 1 *
 Logotron - PicturePoint Version 1.0.001 *
 Logotron Ltd - Junior PinPoint Version 2.0.12.01 *
 Macromedia Director Version 6.0.2 *
 Macromedia Director Version 6.5 *
 Maths Explorer *
 Matrox Graphics Inc. Matrox Control Center Version 4.10.007 *
 Matrox Graphics Inc. mgadnav Version 4.10.007 *
 Matrox Graphics Inc. mgaqdesk Version 4.10.007 *
 Matrox PowerDesk Version 4.10.007 *
 Megapaint *
 Microsoft Backup Version 4.0.952 *
 Microsoft Corporation - Clip Gallery 3.0 for Windows Version 3.0 *
 Microsoft Corporation - Windows Telephony Version 4.10.2000 *
 Microsoft Excel Version 8.0e *
 Microsoft Map Version 8.00.00.01621 *
 Microsoft Office Binder Version 8.0.3501 *
 Microsoft Office Version 8.0 *
 Microsoft Outlook Version 8.04 *
 Microsoft Photo Editor Version 3.0 *
 Microsoft PowerPoint for Windows Version 8.0b *
 Microsoft Registration Wizard Version 2.0 *
 Microsoft Windows Scripting Host Version 5.0.531.7 *
 Microsoft® Schedule+ for Windows 95(TM) Version 7.5 *
 Microsoft® Word for Windows® 97 Version 8.0b *
 NDPS *
 Novell Client Login for 32-bit Windows Version 1.00.07 *
 Progressive Networks, Inc. - RealAudio® Player (32-bit) Version 2.1 Version 2.1.1.9 *
 Resarch Machine plc - Colour Options Version 1, 1, 0, 0 *
 Research Machines plc - Talking First Word Version 1.01.0019 *
 Roger Wagner Publishing, Inc. - HyperStudio Version 3.2 *
 RWORLD.EXE *
 Silica Software Systems - Dazzle Application Version 1, 4, 1, 0 *
 Sonnetech Ltd. - Colorific for Windows 95 Version 4.10.007 *
 Superdisk *
 SuperLogo *
 Symantec Core Technology Version 20.0.0.197 *
 Symantec Corporation - Norton AntiVirus Core Technology Version 5.3.0.168 *
 Symantec Corporation - Norton AntiVirus Version 5.3.2.50 *
 Texttease *
 Tips and Tour *
 Wang Laboratories, Inc. - Imaging for Windows 95 Version 1.01.20136 *

Computer Profile Summary

Computer Name: Pc03 (in WORKGROUP)

Profile Date:Monday, June 23, 2003 15:18:54
Advisor Version:6.0c
Windows Logon:admin

Operating System

Windows 95 B (OSR2) (build 4.3.1212)

Processor ^a

400 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Drives

4.20 Gigabytes Usable Hard Drive
Capacity
2.40 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
TEAC CD-540E [CD-ROM drive]
Generic floppy disk drive (3.5")

WDC AC14300R [Hard drive] (4.31
GB) -- drive 0

System Model

Compaq Deskpro EP/SB Series
System Serial Number: 8910CL923815
Asset Tag: 8910CL923815
Chassis Serial Number: 8910CL923815

Main Circuit Board ^b

Board: Compaq 046Ch
Serial Number: 8910CL923815
Bus Clock: 66 megahertz
BIOS: Compaq 686T1 12/09/98

Memory Modules ^{c,d}

64 Megabytes Installed Memory

Slot 'DIMM #1:J1' has 32 MB
Slot 'DIMM #2:J2' has 32 MB

Local Drive Volumes

c: (on drive 0)	2.11 GB	302 MB free
d: (on drive 0)	2.10 GB	2.10 GB free

Logins

No details available

Network Drives

**mounted by admin at 06/23/03
15:18:34**

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free

z: \\smrcp\sys 507 333 MB
MB free

Installed Microsoft Hotfixes

- UPD001 (OLE 32 update)
- UPD002 (Shell update)
- UPD003 (Common dialog update for Windows 3.1 print drivers)
- UPD004 (File and printer sharing update for Microsoft Networks)
- UPD005 (File and printer sharing update for Netware Networks)
- UPD006 (Vredir update for Samba UNIX servers)
- UPD007 (Enhanced password cache security update)
- UPD008 (System Agent update)
- UPD010 (Printer Port update)

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
Intel 82371AB/EB PCI Bus Master IDE Controller
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)

Bus Adapters

Intel 82371AB/EB PCI to USB
Universal Host Controller

Communications

D-Link DE220 ISA PnP LAN adapter
Network Card MAC Address:
00:80:C8:D9:1D:8E
Network IP Address: 172.19.44.24 / 24

Printers

EPSON Stylus COLOR 640 on \\PC01\Epson
HP Color LaserJet 4550 on \\Smrcp_tree\Hp Colour.smrcp PCL 6
HP LaserJet 2100 Series PCL on 172.19.44.150 5e

Display

XPERT 98 AGP 2X (English) [Display adapter]
COMPAQ S700 [Monitor] (16.3"vis, s/n 848CD34TA058, November 1998)

Multimedia

Creative Gameport Joystick
Creative Sound Blaster 16 PCI
Sound Blaster 16 PCI Legacy Device

Other Devices

Avantis CD-ROM Controller
Standard 101/102-Key or Microsoft Natural Keyboard
Standard PS/2 Port Mouse
USB Root Hub

Software Licenses

Microsoft - 69000-OEM-8298537-
Encarta 98 68802
Encyclopedia
Microsoft - 71929-OEM-2000014-

Internet Explorer12345
 Microsoft - MS 53233-270-4527505-
 Office 97 57808
 Microsoft - 32498-OEM-0039225-
 Windows 95 B 45893
 (OSR2)

Software Versions

Adobe Acrobat Version 3.0.000*	Microsoft Corporation - DirectShow Version 6.01.05.0130*
Apple Computer, Inc. MoviePlayer Application Version 3, 0, 0, 1*	Microsoft Corporation - Microsoft Internet Explorer Version 5.00.2014.200*
Apple Computer, Inc. PictureViewer Application Version 3, 0, 0, 1*	Microsoft Corporation - Windows Telephony Version 4.10.2000*
Avantis CD Installation Wizard Version 3.2.*	Microsoft Encarta Version 6.00.43.00013*
Avantis CDsPlayer Version 3.2.*	Microsoft Excel Version 8.0e*
Avantis Ltd - CDserve Monitor Application Version 3.23*	Microsoft Map Version 8.00.00.01621*
Avantis Ltd. - CDserve Version 3.2.*	Microsoft Office Binder Version 8.0.3501 *
Banner Blue Software Incorporated - Microsoft Organization Chart Version 2,0,0,1016*	Microsoft Office Version 8.0*
Belarc, Inc. - BelManage Client Version 6.0c*	Microsoft Outlook Version 8.04*
Crick Software Ltd - CLICKER 3 Version 3.06.0007*	Microsoft Photo Editor Version 3.0*
DataTree Application Version 1, 0, 0, 1*	Microsoft PowerPoint for Windows Version 8.0b*
Dictionary Editor*	Microsoft Registration Wizard Version 2.0 *
Garden!*	Microsoft Windows Scripting Host Version 5.0.531.7*
GENI Application Version 2, 0, 0, 1*	Microsoft® Schedule+ for Windows 95(TM) Version 7.5*
Genigraphics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0*	Microsoft® Word for Windows® 97 Version 8.0b*
Hewlett Packard Add JetDirect Printer Version 1, 0, 0, 1*	NDPS*
Install Microsoft Internet Explorer*	Novell Client Login for 32-bit Windows Version 1.00.07*
InstallShield Deinstaller Version 2.20.914.0*	Progressive Networks, Inc. - RealAudio® Player (32-bit) Version 2.1 Version 2.1.1.9 *
InstallShield unInstaller Version 2.20.924.0*	Resarch Machine plc - Colour Options Version 1, 1, 0, 0*
Intel DMI Explorer Version 1.11*	Research Machines plc - Talking First Word Version 1.01.0019*
LAUNCHER Application Version 1, 0, 0, 1*	Roger Wagner Publishing, Inc. - HyperStudio Version 3.2*
Logotron - PicturePoint Version 1.0.001*	RWORLD.EXE*
Logotron Ltd - Junior PinPoint Version 2.0.12.01*	Silica Software Systems - Dazzle Application Version 1, 4, 1, 0*
Macromedia Director Version 6.0.2*	Sonnetech Ltd. - Colorific for Windows 95 Version 4.10.007*
Macromedia Director Version 6.5*	Superdisk*
Macromedia, Inc. - Flash 4.0 Version 4,0,7,0*	SuperLogo*
Maths Explorer*	Symantec Core Technology Version 20.0.0.197*
Matrox Graphics Inc. Matrox Control Center Version 4.10.007*	Symantec Corporation - Norton AntiVirus Core Technology Version 5.3.0.168*
Matrox Graphics Inc. mgadnav Version 4.10.007*	Symantec Corporation - Norton AntiVirus Version 5.3.2.50*
Matrox Graphics Inc. mgaqdesk Version 4.10.007*	Textease*
Matrox PowerDesk Version 4.10.007*	The Microsoft® Network Version 1.60.0*
Megapaint*	Tips and Tour*
Microsoft Backup Version 4.0.952*	

Microsoft Corporation - Clip Gallery 3.0
for Windows Version 3.0*

Wang Laboratories, Inc. - Imaging for
Windows 95 Version 1.01.20136*

* Click to see where software is installed.

- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.
Legal notice. U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name:Pc04 (in WORKGROUP)

Profile Date:Monday, June 23, 2003 15:09:55

Advisor Version:6.0c

Windows Logon:admin

Operating System

Windows 95 B (OSR2) (build 4.3.1212)

Processor ^a

400 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Drives

4.20 Gigabytes Usable Hard Drive Capacity
2.37 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
TEAC CD-540E [CD-ROM drive]
Generic floppy disk drive (3.5")

WDC AC14300R [Hard drive] (4.31 GB) -- drive 0

Logins

No details available

System Model

Compaq Deskpro EP/SB Series
System Serial Number: 8911CL920323
Asset Tag: 8911CL920323
Chassis Serial Number: 8911CL920323

Main Circuit Board ^b

Board: Compaq 046Ch
Serial Number: 8911CL920323
Bus Clock: 66 megahertz
BIOS: Compaq 686T1 12/09/98

Memory Modules ^{c,d}

64 Megabytes Installed Memory

Slot 'DIMM #1:J1' has 32 MB
Slot 'DIMM #2:J2' has 32 MB

Local Drive Volumes

c: (on drive 0)	2.11 GB	274 MB free
d: (on drive 0)	2.10 GB	2.10 GB free

Network Drives

mounted by admin at 06/23/03 15:09:32

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Installed Microsoft Hotfixes

UPD001 (OLE 32 update)

Printers

EPSON Stylus COLOR 640 on \\PC01\Epson

- UPD002 (Shell update)
- UPD003 (Common dialog update for Windows 3.1 print drivers)
- UPD004 (File and printer sharing update for Microsoft Networks)
- UPD005 (File and printer sharing update for Netware Networks)
- UPD006 (Vredir update for Samba UNIX servers)
- UPD007 (Enhanced password cache security update)
- UPD008 (System Agent update)
- UPD010 (Printer Port update)

HP Color LaserJet 4550 PCL 6 on \\Smrcp_tree\Hp Colour.SMRCP
 HP DeskJet 550C Printer on LPT1:
 HP LaserJet 2100 Series PCL 5e on 172.19.44.150

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
 Intel 82371AB/EB PCI Bus Master IDE Controller
 Primary IDE controller (dual fifo)
 Secondary IDE controller (dual fifo)

Bus Adapters

Intel 82371AB/EB PCI to USB
 Universal Host Controller

Communications

D-Link DE220 ISA PnP LAN adapter
 Network Card MAC Address: 00:80:C8:D8:CB:B6
 Network IP Address: 172.19.44.26 / 24

Display

Matrox MGA -G100 AGP [Display adapter]
 COMPAQ S700 [Monitor] (16.3"vis, s/n 903CD61TN673, January 1999)

Multimedia

Creative Gameport Joystick
 Creative Sound Blaster 16 PCI
 Sound Blaster 16 PCI Legacy Device

Other Devices

Avantis CD-ROM Controller
 Standard 101/102-Key or Microsoft Natural Keyboard
 Standard PS/2 Port Mouse
 USB Root Hub

Software Licenses

Microsoft - 69000-OEM-3325627-08525
 Encarta 98

Encyclopedia
 Microsoft - 71929-OEM-2000014-
 Internet Explorer12345
 Microsoft - MS 53233-270-4527505-
 Office 97 57808
 Microsoft - 33632-045-0277192-
 Publisher 3.0 13370
 CD
 Microsoft - 32498-OEM-0039225-
 Windows 95 B 45893
 (OSR2)

Software Versions

Adobe Acrobat Version 3.0.000*	Microsoft Corporation - Windows
Apple Computer, Inc. MoviePlayer	Telephony Version 4.10.2000 *
Application Version 3, 0, 0, 1 *	Microsoft Encarta Version 6.00.43.00013 *
Apple Computer, Inc. PictureViewer	Microsoft Excel Version 8.0e *
Application Version 3, 0, 0, 1 *	Microsoft Map Version 8.00.00.01621 *
Avantis CD Installation Wizard Version	Microsoft Office Binder Version 8.0.3501
3.2 *	*
Avantis CDsPlayer Version 3.2 *	Microsoft Office Version 8.0 *
Avantis Ltd - CDserve Monitor	Microsoft Outlook Version 8.04 *
Application Version 3.23 *	Microsoft Photo Editor Version 3.0 *
Avantis Ltd. - CDserve Version 3.2 *	Microsoft PowerPoint for Windows
Banner Blue Software Incorporated -	Version 8.0b *
Microsoft Organization Chart Version	Microsoft Publisher for Windows® 95
2,0,0,1016 *	Version 3.0 Version 3.0 *
Belarc, Inc. - BelManage Client Version	Microsoft Registration Wizard Version 2.0
6.0c *	*
Centrinity Inc. - FirstClass® Client	Microsoft Windows Scripting Host
Version 7.008 *	Version 5.0.531.7 *
Convert Application Version 1, 0, 0, 1 *	Microsoft® Schedule+ for Windows
Crick Software Ltd - CLICKER 3 Version	95(TM) Version 7.5 *
3.06.0007 *	Microsoft® Word for Windows® 97
DataTree Application Version 1, 0, 0, 1 *	Version 8.0b *
Dictionary Editor *	MP Express Player Startup *
DK Interactive Learning Sampler 10.2 -	MP Express Startup *
1999 Version 10.02.000 *	NDPS *
GENI Application Version 2, 0, 0, 1 *	NewSoft Technology Corporation -
Genigraphics®, An In Focus Systems ®	PageManager Version 4.20 *
Company - GraphicsLink(TM) for	NewSoft Technology Corporation - Presto!
Windows Version 8.0 *	ProImage Plus Version 4, 1, 5, 0 *
Hewlett Packard Add JetDirect Printer	Novell Client Login for 32-bit Windows
Version 1, 0, 0, 1 *	Version 1.00.07 *
Install Acrobat Reader *	Presto! PageType *
Install Microsoft Internet Explorer *	Progressive Networks, Inc. - RealAudio®
InstallShield Deinstaller Version	Player (32-bit) Version 2.1 Version 2.1.1.9
2.20.914.0 *	*
InstallShield unInstaller Version	Resarch Machine plc - Colour Options
2.20.926.0 *	Version 1, 1, 0, 0 *
Intel DMI Explorer Version 1.11 *	Research Machines plc - Talking First
LAUNCHER Application Version 1, 0, 0,	Word Version 1.01.0019 *
1 *	Roger Wagner Publishing, Inc. -
Logotron - PicturePoint Version 1.0.001 *	HyperStudio Version 3.2 *
Logotron Ltd - Junior PinPoint Version	RWORLD.EXE *
2.0.12.01 *	Silica Software Systems - Dazzle
Macromedia Director Version 6.0.2 *	Application Version 1, 4, 1, 0 *
Macromedia Director Version 6.5 *	Sonnetech Ltd. - Colorific for Windows 95
Macromedia, Inc. - Flash 4.0 Version	Version 4.10.007 *
4,0,7,0 *	Superdisk *

Maths Explorer *	SuperLogo *
Matrox Graphics Inc. Matrox Control Center Version 4.10.007 *	Symantec Core Technology Version 20.0.0.197 *
Matrox Graphics Inc. mgadnav Version 4.10.007 *	Symantec Corporation - Norton AntiVirus Core Technology Version 5.3.0.168 *
Matrox Graphics Inc. mgaqdesk Version 4.10.007 *	Symantec Corporation - Norton AntiVirus Version 5.3.2.50 *
Matrox PowerDesk Version 4.10.007 *	Textease *
Megapaint *	The Microsoft® Network Version 1.60.0 *
Microsoft Backup Version 4.0.952 *	Tips and Tour *
Microsoft Corporation - Clip Gallery 3.0 for Windows Version 3.0 *	VistaShuttle *
Microsoft Corporation - DirectShow Version 6.01.05.0130 *	Wang Laboratories, Inc. - Imaging for Windows 95 Version 1.01.20136 *
Microsoft Corporation - Microsoft Internet Explorer Version 5.00.2014.200 *	

* Click to see where software is installed.

- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.

[Legal notice](#). U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name:Pc05 (in WORKGROUP)

Profile Date:Monday, June 23, 2003 14:38:05

Advisor Version:6.0c

Windows Logon:admin

Operating System

Windows 95 B (OSR2) (build 4.3.1212)

Processor ^a

400 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Drives

4.20 Gigabytes Usable Hard Drive Capacity
2.75 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
TEAC CD-540E [CD-ROM drive]
Generic floppy disk drive (3.5")

WDC AC14300R [Hard drive] (4.31 GB) -- drive 0

Logins

No details available

System Model

Compaq Deskpro EP/SB Series
System Serial Number: 8911CL929195
Asset Tag: 8911CL929195
Chassis Serial Number: 8911CL929195

Main Circuit Board ^b

Board: Compaq 046Ch
Serial Number: 8911CL929195
Bus Clock: 66 megahertz
BIOS: Compaq 686T1 12/09/98

Memory Modules ^{c,d}

64 Megabytes Installed Memory

Slot 'DIMM #1:J1' has 32 MB
Slot 'DIMM #2:J2' has 32 MB

Local Drive Volumes

c: (on drive 0)	2.11 GB	655 MB free
d: (on drive 0)	2.10 GB	2.10 GB free

Network Drives

mounted by admin at 06/23/03 14:37:48

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Installed Microsoft Hotfixes

UPD001 (OLE 32 update)

Printers

EPSON Stylus COLOR 640 on \\PC01\Epson

- UPD002 (Shell update)
- UPD003 (Common dialog update for Windows 3.1 print drivers)
- UPD004 (File and printer sharing update for Microsoft Networks)
- UPD005 (File and printer sharing update for Netware Networks)
- UPD006 (Vredir update for Samba UNIX servers)
- UPD007 (Enhanced password cache security update)
- UPD008 (System Agent update)
- UPD010 (Printer Port update)

HP Color LaserJet 4550 PCL 6
 on \\Smrcp_tree\Hp Colour.SMRCP

HP LaserJet 2100 Series PCL 5e
 on 172.19.44.150

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
 Intel 82371AB/EB PCI Bus Master IDE Controller
 Primary IDE controller (dual fifo)
 Secondary IDE controller (dual fifo)

Bus Adapters

Intel 82371AB/EB PCI to USB
 Universal Host Controller

Communications

D-Link DE220 ISA PnP LAN adapter
 Network Card MAC Address:
 00:80:C8:D8:BF:14
 Network IP Address: 172.19.44.20 / 24

Display

Matrox MGA -G100 AGP [Display adapter]
 COMPAQ S700 [Monitor] (16.3"vis, s/n 903CD61TN673, January 1999)

Multimedia

Creative Gameport Joystick
 Creative Sound Blaster 16 PCI
 Sound Blaster 16 PCI Legacy Device

Other Devices

Avantis CD-ROM Controller
 Standard 101/102-Key or Microsoft Natural Keyboard
 Standard PS/2 Port Mouse
 USB Root Hub

Software Licenses

Microsoft - 71929-OEM-2000014-Internet Explorer12345
 Microsoft - MS 53233-270-4527505-Office 97 57808
 Microsoft - 32498-OEM-0039225-Windows 95 B 45893 (OSR2)

Software Versions

Adobe Acrobat Version 3.0.000*	Microsoft Corporation - Windows
Apple Computer, Inc. MoviePlayer	Telephony Version 4.10.2000 *
Application Version 3, 0, 0, 1 *	Microsoft Excel Version 8.0e *
Apple Computer, Inc. PictureViewer	Microsoft Map Version 8.00.00.01621*

Application Version 3, 0, 0, 1 [*](#)
Avantis CD Installation Wizard Version 3.2 [*](#)
Avantis CDsPlayer Version 3.2 [*](#)
Avantis Ltd - CDserve Monitor Application Version 3.23 [*](#)
Avantis Ltd. - CDserve Version 3.2 [*](#)
Banner Blue Software Incorporated - Microsoft Organization Chart Version 2,0,0,1016 [*](#)
Belarc, Inc. - BelManage Client Version 6.0c [*](#)
Crick Software Ltd - CLICKER 3 Version 3.06.0007 [*](#)
DataTree Application Version 1, 0, 0, 1 [*](#)
Dictionary Editor [*](#)
Garden! [*](#)
Genigraphics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0 [*](#)
Hewlett Packard Add JetDirect Printer Version 1, 0, 0, 1 [*](#)
InstallShield Deinstaller Version 2.20.914.0 [*](#)
InstallShield unInstaller Version 2.20.924.0 [*](#)
Intel DMI Explorer Version 1.11 [*](#)
LAUNCHER Application Version 1, 0, 0, 1 [*](#)
Logotron - PicturePoint Version 1.0.001 [*](#)
Logotron Ltd - Junior PinPoint Version 2.0.12.01 [*](#)
Macromedia Director Version 6.0.2 [*](#)
Macromedia Director Version 6.5 [*](#)
Macromedia, Inc. - Flash 4.0 Version 4,0,7,0 [*](#)
Maths Explorer [*](#)
Matrox Graphics Inc. Matrox Control Center Version 4.10.007 [*](#)
Matrox Graphics Inc. mgadnav Version 4.10.007 [*](#)
Matrox Graphics Inc. mgaqdesk Version 4.10.007 [*](#)
Matrox PowerDesk Version 4.10.007 [*](#)
Megapaint [*](#)
Microsoft Backup Version 4.0.952 [*](#)
Microsoft Corporation - Clip Gallery 3.0 for Windows Version 3.0 [*](#)
Microsoft Corporation - DirectShow Version 6.01.05.0130 [*](#)
Microsoft Corporation - Microsoft Internet Explorer Version 5.00.2014.200 [*](#)
Microsoft Office Binder Version 8.0.3501 [*](#)
Microsoft Office Version 8.0 [*](#)
Microsoft Outlook Version 8.04 [*](#)
Microsoft Photo Editor Version 3.0 [*](#)
Microsoft PowerPoint for Windows Version 8.0b [*](#)
Microsoft Registration Wizard Version 2.0 [*](#)
Microsoft Windows Scripting Host Version 5.0.531.7 [*](#)
Microsoft® Schedule+ for Windows 95(TM) Version 7.5 [*](#)
Microsoft® Word for Windows® 97 Version 8.0b [*](#)
Monitor [*](#)
NDPS [*](#)
Newman College - Bounce Version 1.00 [*](#)
Novell Client Login for 32-bit Windows Version 1.00.07 [*](#)
Progressive Networks, Inc. - RealAudio® Player (32-bit) Version 2.1 Version 2.1.1.9 [*](#)
Resarch Machine plc - Colour Options Version 1, 1, 0, 0 [*](#)
Research Machines plc - Talking First Word Version 1.01.0019 [*](#)
Roger Wagner Publishing, Inc. - HyperStudio Version 3.2 [*](#)
RWORLD.EXE [*](#)
Sherston Software Playbook [*](#)
Silica Software Systems - Dazzle Application Version 1, 4, 1, 0 [*](#)
Sonnetch Ltd. - Colorific for Windows 95 Version 4.10.007 [*](#)
Superdisk [*](#)
SuperLogo [*](#)
Symantec Core Technology Version 20.0.0.197 [*](#)
Symantec Corporation - Norton AntiVirus Core Technology Version 5.3.0.168 [*](#)
Symantec Corporation - Norton AntiVirus Version 5.3.2.50 [*](#)
Textease [*](#)
The Microsoft® Network Version 1.60.0 [*](#)
Tips and Tour [*](#)
Wang Laboratories, Inc. - Imaging for Windows 95 Version 1.01.20136 [*](#)

Computer Profile Summary

Computer Name: Pc06 (in WORKGROUP)

Profile Date: Monday, June 23, 2003 15:23:37

Advisor Version: 6.0c

Windows Logon: admin

Operating System

Windows 95 B (OSR2) (build 4.3.1212)

System Model

Compaq Deskpro EP/SB Series
System Serial Number: 8911CL929077
Asset Tag: 8911CL929077
Chassis Serial Number: 8911CL929077

Processor ^a

400 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Main Circuit Board ^b

Board: Compaq 046Ch
Serial Number: 8911CL929077
Bus Clock: 66 megahertz
BIOS: Compaq 686T1 12/09/98

Drives

4.20 Gigabytes Usable Hard Drive Capacity
2.31 Gigabytes Hard Drive Free Space
AVANTIS CDSERVE [CD-ROM drive]
TEAC CD-540E [CD-ROM drive]
Generic floppy disk drive (3.5")
WDC AC14300R [Hard drive] (4.31 GB) -- drive 0

Memory Modules ^{c,d}

64 Megabytes Installed Memory
Slot 'DIMM #1:J1' has 32 MB
Slot 'DIMM #2:J2' has 32 MB

Local Drive Volumes

c: (on drive 0)	2.11 GB	217 MB free
d: (on drive 0)	2.10 GB	2.10 GB free

Logins

No details available

Network Drives

mounted by admin at 06/23/03
15:23:13

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free

z: \\smrcp\sys 507 333 MB
MB free

Installed Microsoft Hotfixes

- UPD001 (OLE 32 update)
- UPD002 (Shell update)
- UPD003 (Common dialog update for Windows 3.1 print drivers)
- UPD004 (File and printer sharing update for Microsoft Networks)
- UPD005 (File and printer sharing update for Netware Networks)
- UPD006 (Vredir update for Samba UNIX servers)
- UPD007 (Enhanced password cache security update)
- UPD008 (System Agent update)
- UPD010 (Printer Port update)

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
Intel 82371AB/EB PCI Bus Master IDE Controller
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)

Bus Adapters

Intel 82371AB/EB PCI to USB
Universal Host Controller

Communications

D-Link DE220 ISA PnP LAN adapter
Network Card MAC Address:
00:80:C8:D9:20:A8
Network IP Address: 172.19.44.15 / 24

Printers

EPSON Stylus COLOR 640 on \\PC01\Epson
HP Color LaserJet 4550 PCL 6 on \\Smrcp\HP_COLOUR
HP DeskJet 550C Printer on LPT1:
HP LaserJet 2100 Series on 172.19.44.150 PCL 5e
MS Publisher Color Printer on FILE:
MS Publisher Imagesetter on FILE:

Display

Matrox MGA -G100 AGP [Display adapter]
COMPAQ S700 [Monitor] (16.3"vis, s/n 903CD61TN673, January 1999)

Multimedia

Creative Gameport Joystick
Creative Sound Blaster 16 PCI
Sound Blaster 16 PCI Legacy Device

Other Devices

Avantis CD-ROM Controller
Standard 101/102-Key or Microsoft Natural Keyboard
Standard PS/2 Port Mouse
USB Root Hub

Software Licenses

Microsoft - 71929-OEM-2000014-Internet Explorer12345
Microsoft - MS 53233-270-4527505-Office 97 57808
Microsoft - 80672-045-0104394-

Publisher 98 CD 21008
Microsoft - 32498-OEM-0039225-
Windows 95 B 45893
(OSR2)

Software Versions

Adobe Acrobat Version 3.0.000*	Microsoft Excel Version 8.0e*
Avantis CD Installation Wizard Version 3.2*	Microsoft Map Version 8.00.00.01621*
Avantis CDPlayer Version 3.2*	Microsoft Office Binder Version 8.0.3501*
Avantis Ltd - CDserve Monitor Application Version 3.23*	Microsoft Office Version 8.0.3512*
Avantis Ltd. - CDserve Version 3.2*	Microsoft Outlook Version 8.04*
Banner Blue Software Incorporated - Microsoft Organization Chart Version 2,0,0,1016*	Microsoft Photo Editor Version 3.0*
Belarc, Inc. - BelManage Client Version 6.0c*	Microsoft PowerPoint for Windows Version 8.0b*
Convert Application Version 1, 0, 0, 1*	Microsoft Registration Wizard Version 2.0*
Crick Software Ltd - CLICKER 3 Version 3.06.0007*	Microsoft Windows Scripting Host Version 5.0.531.7*
DataTree Application Version 1, 0, 0, 1*	Microsoft® Publisher for Windows® 95 Version 5.0 Version 5.0*
Dictionary Editor*	Microsoft® Schedule+ for Windows 95(TM) Version 7.5*
Geniographics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0*	Microsoft® Word for Windows® 97 Version 8.0b*
Hewlett Packard Add JetDirect Printer Version 1, 0, 0, 1*	NDPS*
Install Acrobat Reader*	NewSoft Technology Corporation - PageManager Version 4.20*
InstallShield Deinstaller Version 2.20.914.0*	NewSoft Technology Corporation - Presto! ProImage Plus Version 4, 1, 5, 0*
InstallShield unInstaller Version 2.20.924.0*	Novell Client Login for 32-bit Windows Version 1.00.07*
Intel DMI Explorer Version 1.11*	Presto! PageType*
LAUNCHER Application Version 1, 0, 0, 1*	Progressive Networks, Inc. - RealAudio® Player (32-bit) Version 2.1 Version 2.1.1.9*
Logotron - PicturePoint Version 1.0.001*	Resarch Machine plc - Colour Options Version 1, 1, 0, 0*
Logotron Ltd - Junior PinPoint Version 2.0.12.01*	Research Machines plc - Talking First Word Version 1.01.0019*
Macromedia Director Version 6.0.2*	RWORLD.EXE*
Macromedia, Inc. - Flash 4.0 Version 4,0,7,0*	Silica Software Systems - Dazzle Application Version 1, 4, 1, 0*
Maths Explorer*	Sonnetech Ltd. - Colorific for Windows 95 Version 4.10.007*
Matrox Graphics Inc. Matrox Control Center Version 4.10.007*	Superdisk*
Matrox Graphics Inc. mgadnav Version 4.10.007*	SuperLogo*
Matrox Graphics Inc. mgaqdesk Version 4.10.007*	Symantec Core Technology Version 20.0.0.197*
Matrox PowerDesk Version 4.10.007*	Symantec Corporation - Norton AntiVirus Core Technology Version 5.3.0.168*
Megapaint*	Symantec Corporation - Norton AntiVirus Version 5.3.2.50*
Microsoft Backup Version 4.0.952*	Textease*
Microsoft Corporation - Clip Gallery 4.0 for Windows Version 4.0*	The Microsoft® Network Version 1.60.0*
Microsoft Corporation - DirectShow Version 6.01.05.0130*	Tips and Tour*
Microsoft Corporation - Microsoft Internet Explorer Version 5.00.2014.200*	VistaShuttle*
Microsoft Corporation - Windows Telephony Version 4.10.2000*	Wang Laboratories, Inc. - Imaging for Windows 95 Version 1.01.20136*

* Click to see where software is installed.

- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.
[Legal notice](#). U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name:Pc07 (in WORKGROUP)

Profile Date:Monday, June 23, 2003 14:56:03

Advisor Version:6.0c

Windows Logon:admin

Operating System

Windows 95 B (OSR2) (build 4.3.1212)

Processor ^a

400 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Drives

4.20 Gigabytes Usable Hard Drive Capacity
2.63 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
TEAC CD-540E [CD-ROM drive]
Generic floppy disk drive (3.5")

WDC AC14300R [Hard drive] (4.31 GB) -- drive 0

Logins

No details available

System Model

Compaq Deskpro EP/SB Series
System Serial Number: 8911CL929081
Asset Tag: 8911CL929081
Chassis Serial Number: 8911CL929081

Main Circuit Board ^b

Board: Compaq 046Ch
Serial Number: 8911CL929081
Bus Clock: 66 megahertz
BIOS: Compaq 686T1 12/09/98

Memory Modules ^{c,d}

64 Megabytes Installed Memory

Slot 'DIMM #1:J1' has 32 MB
Slot 'DIMM #2:J2' has 32 MB

Local Drive Volumes

c: (on drive 0)	2.11 GB	531 MB free
d: (on drive 0)	2.10 GB	2.10 GB free

Network Drives

mounted by admin at 06/23/03 14:55:44

f: \\smrcp\sys	507 MB	334 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	334 MB free

Installed Microsoft Hotfixes

UPD001 (OLE 32 update)

Printers

EPSON Stylus COLOR 640 on \\PC01\Epson

- UPD002 (Shell update)
- UPD003 (Common dialog update for Windows 3.1 print drivers)
- UPD004 (File and printer sharing update for Microsoft Networks)
- UPD005 (File and printer sharing update for Netware Networks)
- UPD006 (Vredir update for Samba UNIX servers)
- UPD007 (Enhanced password cache security update)
- UPD008 (System Agent update)
- UPD010 (Printer Port update)

HP Color LaserJet 4550 PCL 6
 on \\Smrcp_tree\Hp Colour.SMRCP

HP LaserJet 2100 Series PCL 5e
 on 172.19.44.150

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
 Intel 82371AB/EB PCI Bus Master IDE Controller
 Primary IDE controller (dual fifo)
 Secondary IDE controller (dual fifo)

Bus Adapters

Intel 82371AB/EB PCI to USB
 Universal Host Controller

Communications

D-Link DE220 ISA PnP LAN adapter
 Network Card MAC Address:
 00:80:C8:D8:C8:C1
 Network IP Address: 172.19.44.16 / 24

Display

Matrox MGA -G100 AGP [Display adapter]
 COMPAQ S700 [Monitor] (16.3"vis, s/n 903CD61TN673, January 1999)

Multimedia

Creative Gameport Joystick
 Creative Sound Blaster 16 PCI
 Sound Blaster 16 PCI Legacy Device

Other Devices

Avantis CD-ROM Controller
 Standard 101/102-Key or Microsoft Natural Keyboard
 Standard PS/2 Port Mouse
 USB Root Hub

Software Licenses

Microsoft - 71929-OEM-2000014-Internet Explorer12345
 Microsoft - MS 53233-270-4527505-Office 97 57808
 Microsoft - 32498-OEM-0039225-Windows 95 B 45893 (OSR2)

Software Versions

Adobe Acrobat Reader Version 5.0.5.0*	Microsoft Corporation - Windows
Avantis CD Installation Wizard Version 3.2*	Telephony Version 4.10.2000*
Avantis CD'sPlayer Version 3.2*	Microsoft Excel Version 8.0e*
	Microsoft Map Version 8.00.00.01621*

Avantis Ltd - CDserve Monitor
Application Version 3.23 *
Avantis Ltd. - CDserve Version 3.2 *
Banner Blue Software Incorporated -
Microsoft Organization Chart Version
2,0,0,1016 *
Belarc, Inc. - BelManage Client Version
6.0c *
Crick Software Ltd - CLICKER 3 Version
3.06.0007 *
DataTree Application Version 1, 0, 0, 1 *
Dictionary Editor *
Geniographics®, An In Focus Systems®
Company - GraphicsLink(TM) for
Windows Version 8.0 *
Hewlett Packard Add JetDirect Printer
Version 1, 0, 0, 1 *
InstallShield Deinstaller Version
2.20.914.0 *
InstallShield unInstaller Version
2.20.924.0 *
Intel DMI Explorer Version 1.11 *
LAUNCHER Application Version 1, 0, 0,
1 *
Logotron - PicturePoint Version 1.0.001 *
Logotron Ltd - Junior PinPoint Version
2.0.12.01 *
Macromedia Director Version 6.0.2 *
Macromedia Director Version 6.5 *
Maths Explorer *
Matrox Graphics Inc. Matrox Control
Center Version 4.10.007 *
Matrox Graphics Inc. mgadnav Version
4.10.007 *
Matrox Graphics Inc. mgaqdesk Version
4.10.007 *
Matrox PowerDesk Version 4.10.007 *
Megapaint *
Microsoft Backup Version 4.0.952 *
Microsoft Corporation - Clip Gallery 3.0
for Windows Version 3.0 *
Microsoft Corporation - DirectShow
Version 6.01.05.0130 *
Microsoft Corporation - Microsoft Internet
Explorer Version 5.00.2014.200 *
Microsoft Office Binder Version 8.0.3501
*
Microsoft Office Version 8.0 *
Microsoft Outlook Version 8.04 *
Microsoft Photo Editor Version 3.0 *
Microsoft PowerPoint for Windows
Version 8.0b *
Microsoft Registration Wizard Version 2.0
*
Microsoft Windows Scripting Host Version
5.0.531.7 *
Microsoft® Schedule+ for Windows
95(TM) Version 7.5 *
Microsoft® Word for Windows® 97
Version 8.0b *
NDPS *
Novell Client Login for 32-bit Windows
Version 1.00.07 *
Progressive Networks, Inc. - RealAudio®
Player (32-bit) Version 2.1 Version 2.1.1.9
*
Resarch Machine plc - Colour Options
Version 1, 1, 0, 0 *
Research Machines plc - Talking First
Word Version 1.01.0019 *
RWORLD.EXE *
Silica Software Systems - Dazzle
Application Version 1, 4, 1, 0 *
Sonnetech Ltd. - Colorific for Windows 95
Version 4.10.007 *
Superdisk *
SuperLogo *
Symantec Core Technology Version
20.0.0.197 *
Symantec Corporation - Norton AntiVirus
Core Technology Version 5.3.0.168 *
Symantec Corporation - Norton AntiVirus
Version 5.3.2.50 *
Textease *
The Microsoft® Network Version 1.60.0 *
Tips and Tour *
Wang Laboratories, Inc. - Imaging for
Windows 95 Version 1.01.20136 *

Computer Profile Summary

Computer Name: Pc10 (in WORKGROUP)

Profile Date: Monday, June 23, 2003 14:45:37

Advisor Version: 6.0c

Windows Logon: admin

Operating System

Windows 95 B (OSR2) (build 4.3.1212)

Processor ^a

400 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Drives

4.20 Gigabytes Usable Hard Drive Capacity
2.71 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
TEAC CD-540E [CD-ROM drive]
Generic floppy disk drive (3.5")

WDC AC14300R [Hard drive] (4.31 GB) -- drive 0

Logins

No details available

Installed Microsoft Hotfixes

(OLE 32 update)
UPD001
 (Shell update)

System Model

Compaq Deskpro EP/SB Series
System Serial Number: 8911CL923866
Asset Tag: 8911CL923866
Chassis Serial Number: 8911CL923866

Main Circuit Board ^b

Board: Compaq 046Ch
Serial Number: 8911CL923866
Bus Clock: 66 megahertz
BIOS: Compaq 686T1 12/09/98

Memory Modules ^{c,d}

64 Megabytes Installed Memory

Slot 'DIMM #1:J1' has 32 MB
Slot 'DIMM #2:J2' has 32 MB

Local Drive Volumes

c: (on drive 0)	2.11 GB	608 MB free
d: (on drive 0)	2.10 GB	2.10 GB free

Network Drives

mounted by admin at 06/23/03 14:45:11

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Printers

EPSON Stylus COLOR 640 on \\PC01\Epson

LaserJet 4550 \\Smrcp\HP_COLOUR
PCL 6
HP LaserJet
2100 Series on 172.19.44.150
PCL 5e

Controllers

Standard Floppy Disk Controller
Intel 82371AB/EB PCI Bus Master IDE
Controller
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)

Bus Adapters

Intel 82371AB/EB PCI to USB
Universal Host Controller

Communications

D-Link DE220 ISA PnP LAN adapter
Network Card MAC Address:
00:80:C8:D9:23:5B
Network IP Address: 172.19.44.19 / 24

Display

NVIDIA Vanta [Display adapter]
COMPAQ S700 [Monitor] (16.3"vis, s/n
903CD61TO062, January 1999)

Multimedia

Creative Gameport Joystick
Creative Sound Blaster 16 PCI
Sound Blaster 16 PCI Legacy Device

Other Devices

Avantis CD-ROM Controller
Standard 101/102-Key or Microsoft
Natural Keyboard
Standard PS/2 Port Mouse
USB Root Hub

Software Licenses

Eye2eye
Software Ltd - 2616821796
Eye2eye Britain
Microsoft - 71929-OEM-2000014-
Internet Explorer12345
Microsoft - MS 53233-270-4527505-
Office 97 57808
Microsoft - 32498-OEM-0039225-
Windows 95 B 45893
(OSR2)

Software Versions

Garden! *
Genigraphics®, An In Focus Systems®
Company - GraphicsLink(TM) for
Windows Version 8.0 *
Hewlett Packard Add JetDirect Printer
Version 1, 0, 0, 1 *

5.0.531.7 *
Microsoft® Schedule+ for Windows
95(TM) Version 7.5 *
Microsoft® Word for Windows® 97
Version 8.0b *
NDPS *

InstallShield Deinstaller Version 2.20.914.0*	Novell Client Login for 32-bit Windows Version 1.00.07*
InstallShield unInstaller Version 2.20.924.0*	Progressive Networks, Inc. - RealAudio® Player (32-bit) Version 2.1 Version 2.1.1.9*
Intel DMI Explorer Version 1.11*	
LAUNCHER Application Version 1, 0, 0, 1*	Resarch Machine plc - Colour Options Version 1, 1, 0, 0*
Logotron - PicturePoint Version 1.0.001*	Research Machines plc - Talking First Word Version 1.01.0019*
Logotron Ltd - Junior PinPoint Version 2.0.12.01*	RWORLD.EXE*
Macromedia Director Version 6.0.2*	Sherston Software Playbook*
Macromedia Director Version 6.5*	Silica Software Systems - Dazzle Application Version 1, 4, 1, 0*
Macromedia, Inc. - Flash 4.0 Version 4,0,7,0*	Sonetech Ltd. - Colorific for Windows 95 Version 4.10.007*
Maths Explorer*	Superdisk*
Matrox Graphics Inc. Matrox Control Center Version 4.10.007*	SuperLogo*
Matrox Graphics Inc. mgadnav Version 4.10.007*	Symantec Core Technology Version 20.0.0.197*
Matrox Graphics Inc. mgaqdesk Version 4.10.007*	Symantec Corporation - Norton AntiVirus Core Technology Version 5.3.0.168*
Matrox PowerDesk Version 4.10.007*	Symantec Corporation - Norton AntiVirus Version 5.3.2.50*
Megapaint*	Textease*
Microsoft Backup Version 4.0.952*	The Microsoft® Network Version 1.60.0*
Microsoft Corporation - Clip Gallery 3.0 for Windows Version 3.0*	Tips and Tour*
Microsoft Corporation - DirectShow Version 6.01.05.0130*	Wang Laboratories, Inc. - Imaging for Windows 95 Version 1.01.20136*

Computer Profile Summary

*Computer Name:*Pc19 (in WORKGROUP)

*Profile Date:*Monday, June 23, 2003 16:18:30

*Advisor Version:*6.0c

*Windows Logon:*gh

Operating System	System Model
Windows 98 (build 4.10.1998)	Packard Bell NEC Packard Bell Computer P070001901 System Serial Number: C417100346
Processor ^a	Main Circuit Board ^b
225 megahertz Cyrix MII 64 kilobyte primary memory cache 512 kilobyte secondary memory cache	Board: SiS-5598-W877F Bus Clock: 75 megahertz BIOS: Award Software International, Inc. 4.51 PG 10/23/98
Drives	Memory Modules ^{c,d}

3.23 Gigabytes Usable Hard Drive Capacity
1.47 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
GoldStar CD-ROM CRD-8322B
Generic floppy disk drive (3.5")

Generic IDE hard disk drive (3.23 GB) -- drive 0

Logins

No details available

28 Megabytes Installed Memory

Slot '0' has 32 MB
Slot '1' is Empty

Local Drive Volumes

c: (on drive 0)	3.23 GB	1.47 GB free
-----------------	---------	--------------

Network Drives

mounted by gh at 06/23/03 16:18:04

f: \\smrcp\sys	507 MB	334 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	507 MB	334 MB free
z: \\smrcp\sys	507 MB	334 MB free

Installed Microsoft Hotfixes

Internet Explorer

SP1 (SP1)

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)
SiS 5513 Dual PCI IDE Controller

Bus Adapters

SiS 7001 PCI to USB Open Host Controller

Communications

MDP3858-E Modem
SMC EZ Card 10/100 PCI (SMC1211 Series)
Network Card MAC Address:
00:E0:29:5A:10:44
Network IP Address: 172.19.44.36 / 24

Printers

HP Color LaserJet 4550 PCL 6 on \\Smrcp\HP_COLOUR
HP LaserJet 2100 Series PCL 6 on HPLaserJet2100Series
OLICHROME Olivetti JP192 on LPT1:

Display

SiS 5597/5598 [Display adapter]
Packard Bell PBN 1015 [Monitor] (13.2"vis, s/n LEMN84702320, November 1998)

Multimedia

ES1869 Control Interface
ES1869 Plug and Play AudioDrive
Gameport Joystick (no joystick connected)

Other Devices

Avantis CD-ROM Controller
MDP3858 PCI Modem Enumerator
Standard 101/102-Key or Microsoft Natural Keyboard
PS2 (PS/2) [Mouse]
USB Root Hub

Software Licenses

Microsoft - Money 98	68480-OEM-1208613-23458 06099-OEM-0073614-
Microsoft - Windows 98	76564 (Key: BWT4H-KW2C9-K7RVQ-93J7V-J7DPY)
Microsoft - Word for Windows	00000-OEM-0000000-00000
Microsoft - Works 4.5	11195-OEM-0310021-81354

Software Versions

Actua Soccer 2 *	Microsoft Photo Editor Version 3.0 *
Adobe Acrobat Version 3.0.000 *	Microsoft Windows Scripting Host Version 5.0.531.7 *
America Online, Inc. - AOL Instant Messenger (TM) Version 1.0.295 *	Microsoft Works for Windows Version 4.00.03.458 *
Apple Computer, Inc. - QuickTime QuickTime 4.0.1 *	Microsoft® Plus! for Windows® 95 Version 4.40.500 *
AutoStreet 2000 *	Microsoft® Chat Version 2.1 *
AutoStreet 2000 Lite *	Microsoft® FrontPage(TM) Version 2.0.2.1118 *
Avantis CD Installation Wizard Version 3.2 *	Microsoft® Internet Services Version 6.1.33.0 *
Avantis CDsPlayer Version 3.2 *	Microsoft® NetMeeting(TM) Version 2.1 *
Avantis Ltd - CDserve Monitor Application Version 3.23 *	Microsoft® NetShow Version 2.0.0.912 *
Avantis Ltd. - CDserve Version 3.2 *	Microsoft® Word for Windows® 97 Version 8.0 *
Belarc, Inc. - BelManage Client Version 6.0c *	MindVision Software - Installer VISE Version 2.2 *
BVRP Software - PhoneTools Version 2.10 *	MNYIMPRT.EXE *
CompuServe for Windows Version 3.0 *	NDPS *
Configure Media Player *	Netscape Communications NSConf32 Version 4, 0, 0, 1 *
Corel Family & Friends (TM) Version 1.00.0076 *	Netscape Mail Notification *
Corel Family & Friends Reminders(TM) Version 1.00.0076 *	NETSCAPE Version 4.04 *
Corel Photo House (TM) Version 2.00.0347 *	Novell Client Login for 32-bit Windows Version 1.00.05 *
Corel Print House (TM) Version 3.00.0347 *	Novell wm95 Version 1, 0, 0, 1 *
Cyber Patrol Installation *	Olivetti - OLICHROME (TM) Version 3.1.1 *
Dorling Kindersley Multimedia - The Ultimate Human Body 2.0 Version 2.0.40 *	Packard Bell Navigator Version 1.0.7.1 *
	Packard Bell NEC - PB SoftBar Version

Eastman Software, Inc., A Kodak Business	2.1 *
- Imaging for Windows® Version	Packard Bell Nec, Inc. - ClickMe Version
1.01.1311 *	3.2.0.0 *
Event Reminder *	Packard Bell Tutorials Version 1.0.0.0 *
FloorPlan Plus 3D *	PB NETp@ss & Registration *
GOTO Software - WebEarly 98 Version	Peak Interactive EMail 100431.3430
2.01 *	@compuserve.com - Mathematics Version
Hewlett-Packard - Bierfass II Version	1.00 *
3.001.077.0 *	PhotoStudio Lite *
HHRS WP Link *	PhotoStudio Registration *
InstallShield unInstaller Version	PMW.EXE *
2.20.926.0 *	Print Materials *
JP192 Uninstall program *	PrintMaster Web Site *
Logitech Inc. - MouseWare Version 8.02 *	Progressive Networks, Inc. - RealPlayer
Logotron Ltd - Junior PinPoint Version	(32-bit) Version 4.01 Version 4.0.20.155 *
2.0.12.01 *	QuickTime Updater *
Lotus ScreenCam Version 3, 0, 0, 6 *	Science Explorer II *
Macromedia Director Version 5.0 *	Seagate Software, Inc. - Backup *
Macromedia Director Version 7.0.2 *	Serif Clipart Browser Version 3.0.000 *
Macromedia, Inc. - Director 8.5	Serif PagePlus 4.0 Version 96.4.0.1 *
Shockwave Studio Version 8.5.1 *	Symantec Core Technology Version
Macromedia, Inc. - English - "The Mystery	19.0.0.128 *
of Hyphen Hall" *	Symantec Corporation - Norton AntiVirus
Maths Explorer *	Core Technology Version 5.0.0.52 *
Micrografx ABC Graphics Suite Version	Symantec Corporation - Norton AntiVirus
6.00.001 *	Version 5.0.0.48 *
Micrografx Windows Draw Version 4, 0,	Textease *
0, 1 *	The Hutchinson History Reference Suite *
Micrografx, Inc. Photo Magic Version	WaterGate Software Inc. - PC-Doctor For
4.00a *	Windows 3.0 Version 3.0 *
Microsoft Corporation - Clip Gallery 3.0	ZebraSoft, Inc. - Norton Uninstall Deluxe
for Windows Version 3.0 *	Version 1, 0, 0, 1 *
Microsoft Corporation - Windows Internet	ZebraSoft, Inc. - SymMon Module Version
Explorer Version 4.72.3110.0 *	1, 0, 0, 1 *
Microsoft Corporation - Windows	ôRA CREATIVE - Le Compteur Internet
Telephony Version 1.0.501 *	Européen Version 2.20 Build 0512 *
Microsoft Encarta Version 6.00.43.00013 *	
Microsoft Money Version 6.00 *	
Microsoft Multimedia Viewer Version	
2.00 *	

* Click to see where software is installed.

- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.

[Legal notice](#). U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name: Pc20 (in WORKGROUP)

Profile Date: Monday, June 23, 2003 15:12:46

Advisor Version: 6.0c

Windows Logon: admin

Operating System

Windows Millennium Edition (build 4.90.3000)

Processor ^a

666 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Drives

15.34 Gigabytes Usable Hard Drive Capacity
12.78 Gigabytes Hard Drive Free Space

SAMSUNG COMBO SM -304B [CD-ROM drive]

Generic floppy disk drive (3.5")

Generic IDE hard disk drive (15.34 GB)
-- drive 0

Logins

No details available

System Model

TriGem Computer, Inc. Emachines 100

Main Circuit Board ^b

Board: TriGem Computer, Inc. TriGem System Board

Bus Clock: 66 megahertz

BIOS: Phoenix Technologies LTD

Version 1.01 07/05/2000

Memory Modules ^{c,d}

64 Megabytes Installed Memory

Slot 'M1' is Empty

Slot 'M2' has 64 MB

Local Drive Volumes

c: (on drive 0)	15.34 GB	12.78 GB free
-----------------	----------	---------------

Network Drives

mounted by admin at 06/23/03

15:12:15

f: \\smrcp\sys	507 MB	334 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	334 MB free

Installed Microsoft Hotfixes

Printers

COLOR 640 \\PC01\EPSON
Lexmark Z22-Z32 on LPT1:
Series

Controllers

Standard Floppy Disk Controller
Intel 82801AA Bus Master IDE
Controller
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)

Bus Adapters

Intel(r) 82801AA USB Universal Host
Controller

Communications

ND010 Ethernet/Fast Ethernet PCI Bus
Adapter
Network Card MAC Address:
00:10:A7:08:A3:5F
Network IP Address: 172.19.44.27 / 24

Display

Intel(r) 82810 Graphics Controller
[Display adapter]
Default Monitor

Multimedia

AC'97 Driver for Intel(r) 82801AA
Controller
Gameport Joystick (no joystick
connected)
MPU-401 Compatible MIDI Device

Other Devices

Standard 101/102-Key or Microsoft
Natural Keyboard
USB Root Hub

Software Licenses

Adobe - AJW120B7100010-362
ActiveShare
McAfee - L1MW2EI3121Q1272K3R9IY3C6D35JZ2238H2
Scan95
Microsoft -
Interactive 04900-OEM-0000007-00000
Training
Microsoft -
Internet 52782-OEM-0009147-00364
Explorer
Microsoft -
MediaPlayer 52782-OEM-0009147-00364
Microsoft -
MS Office 53233-111-1111111-07079
97
Microsoft -
Windows 52782-OEM-0009147-00364 (Key: MHXVQ-
Millennium R9CCM-C3TCB-T9RGX-GTGFY)
Edition

Software Versions

2simple Software - 2publish Version 1.00 4.90.0.2525 *
*
Microsoft (r) Windows Script Host
2simple Software - 2Simple IVT Version Version 5.1.0.4615 *
1.00 *
Microsoft Corporation - Clip Gallery 3.0
2simple Software - ICT Videos Version for Windows Version 3.0 *
1.00 *
Microsoft Corporation - DirectShow

Adaptec - CD Jewel Version 1.02 (256) *
 Adaptec - DirectCD Version 3.01 (162) *
 Adaptec - Easy CD Creator Version 4.02 (285) *
 Adaptec - Easy CD Creator Version 4.02S (287) *
 Adaptec - Web-CheckUp Version 1.01 (265) *
 Adobe Acrobat Version 4.0.000 *
 Adobe ActiveShare Version 1.03.0001 *
 America Online, Inc. - AOL UK *
 America Online, Inc. - CompuServe UK *
 Apple Computer, Inc. - QuickTime for Windows Version 2.1.2.59 *
 Banner Blue Software Incorporated - Microsoft Organization Chart Version 2,0,0,1016 *
 Belarc, Inc. - BelManage Client Version 6.0c *
 Cinematronics - 3D Pinball Version 4.90.3000.1 *
 Crick Software Ltd - CLICKER 3 Version 3.06.0007 *
 CyberLink Corp. - PowerDVD Version 2.50.1307 *
 Disney's Print Studio, ToyStory2 Version 1, 0, 1, 1 *
 DK Interactive Learning - 20th Century Day by Day Version 01.02.0015 *
 DK Multimedia - Learning Ladder Years 1&2 - Sampler Version 9.00.003 *
 DK Multimedia - My First Dictionary 2.0 Version 2.00 *
 Eastman Software, Inc., A Kodak Business - Imaging for Windows® Version 1.01.1312 *
 Fisher-Marriott Software - STARSPEL Version 1.00.0056 *
 Genigraphics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0 *
 Hewlett-Packard - HP PrecisionScan LTX Version 1.1 *
 Hutchinson Multimedia Encyclopedia 1996 *
 I.R.I.S. SA - readiris Version 5, 0, 0, 1 *
 InstallShield Deinstaller Version 2.20.914.0 *
 InstallShield unInstaller Version 2.20.926.0 *
 Lexmark ColorFine Version 3.2.1 *
 Lexmark Supplies Monitor Version 1, 0, 0, 1 *
 Logotron - PicturePoint Version 1.0.001 *
 Longman Logotron Ltd. - ISE Version 1.0 *
 Macromedia Director Version 5.0 *
 Macromedia Director Version 6.0.2 *
 Macromedia Director Version 7.0.2 *
 Macromedia, Inc. - Flash 4.0 Version 6.4.07.1112 *
 Microsoft Corporation - Internet Explorer Version 5.50.4134.100 *
 Microsoft Corporation - MSN Gaming Zone Version 1.00.523.4 *
 Microsoft Corporation - MSN(tm) Messenger Service Version 2.2 *
 Microsoft Corporation - Spider Version 2, 0, 0, 1 *
 Microsoft Corporation - Windows Installer Version 1.20.1410.0 *
 Microsoft Corporation - Windows Movie Maker Version 1.0.1376.0 *
 Microsoft Corporation - Windows® NetMeeting® Version 3.01 *
 Microsoft Excel Version 8.0 *
 Microsoft Interactive Training Version 3, 4, 1, 95 *
 Microsoft Map Version 8.00.00.01203 *
 Microsoft Office Binder Version 8.0.3501 *
 Microsoft Office Version 8.0 *
 Microsoft Outlook Version 8.0 *
 Microsoft Photo Editor Version 3.0 *
 Microsoft PowerPoint for Windows Version 8.0 *
 Microsoft(R) Windows Media Player Version 7.00.00.1440 *
 Microsoft® Plus! for Windows® 95 Version 4.40.500 *
 Microsoft® Find Fast Version 8.0 *
 Microsoft® Schedule+ for Windows 95(TM) Version 7.0 *
 Microsoft® Word for Windows® 97 Version 8.0 *
 NDPS *
 Network Associates Inc - McAfee VirusScan Version 4.0.3 *
 Network Associates Inc - VirusScan Version 4.0.3 *
 Network Associates Inc. - McAfee VirusScan Version 4.0.3 *
 Network Associates Inc. - VirusScan Version 4.0.3 *
 Network Associates Inc. - VShield Version 4.0.3 *
 Novell Client Login for 32-bit Windows Version 1.00.07 *
 Novell wm95 Version 1, 0, 0, 1 *
 SHARKLD Version 1.0.001 *
 SHARKP2 Version 1.0.001 *
 Software 2000 UnSetup Version 2.1.9.9 *
 System Diagnostic *
 Textease *
 The Learning Company - Reader Rabbit's Key Stage 1, Year 2 Version 1.01 *
 The Learning Company - Reader Rabbit's Math Ages 6-9 Version 1.00 *
 VsecomrEXE *

4,0,7,0*

* Click to see where software is installed.

- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.

Legal notice. U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name: Pc21 (in WORKGROUP)

Profile Date: Monday, June 23, 2003 14:13:53

Advisor Version: 6.0c

Windows Logon: admin

Operating System

Windows 98 SE (build 4.10.2222)

System Model

Packard Bell NEC
00000000000000000000000000000000
P160100401
System Serial Number: G260700195
Asset Tag: 0123ABC
Chassis Serial Number: 50424E

Processor ^a

366 megahertz Intel Celeron
32 kilobyte primary memory cache
128 kilobyte secondary memory cache

Main Circuit Board ^b

Board: Gigabyte i810 1.3A
Bus Clock: 66 megahertz
BIOS: American Megatrends Inc. 1.1K
08/11/99

Drives

4.31 Gigabytes Usable Hard Drive
Capacity
2.46 Gigabytes Hard Drive Free Space

AVANTIS CDSERVE [CD-ROM drive]
GoldStar CD-ROM CRD-8400B
Generic floppy disk drive (3.5")

FUJITSU MPD3043AT [Hard drive]
(4.33 GB) -- drive 0

Memory Modules ^{c,d}

64 Megabytes Installed Memory

Slot '0' has 64 MB
Slot '1' is Empty

Local Drive Volumes

c: (on drive 0)	4.31 GB	2.46 GB free
-----------------	---------	--------------

Logins

No details available

Network Drives

mounted by admin at 06/23/03
14:13:22

f: \\smrcp\sys	507 MB	0 MB free
g: \\smrcp\vol1	2.15 GB	0 MB free
h: \\smrcp\vol1\shared	2.15 GB	0 MB free
z: \\smrcp\sys	507 MB	0 MB free

Installed Microsoft Hotfixes

No details available

Printers

Capture fax
BVRP on FAX:
Extended

[Click here](#) to see all available security

Hotfixes.

- Marks a HotFix that verifies correctly
 - Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Capture Mono
Fax BVRP on FAX:
HP Color on
LaserJet 4550 PCL 6 \\Smrcp\HP_COLOUR
HP DeskJet 690C on LPT1:
HP DeskJet 690C Series on LPT1:
v11.0
HP LaserJet 2100 Series on \\Smrcp\Q1
PCL 6

Controllers

Standard Floppy Disk Controller
Intel(r) 82801AB Ultra ATA Controller
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)

Bus Adapters

Intel(r) 82801AB USB Universal Host Controller

Communications

MR2800 Data Fax Modem
SMC EZ Card 10/100 PCI (SMC1211 Series)
Network Card MAC Address:
00:E0:29:5A:15:96
Network IP Address: 172.19.44.34 / 24

Software Licenses

Microsoft 52265-442-0772991-25906
- Kids
Microsoft 38477-OEM-1147341-71468
99
Microsoft 53233-111-1111111-66691
Office 97
Microsoft 26499-OEM-0077077-74009 (Key:
Windows V9WWQ3D3HGWDGJ26XG9D828G3)
98 SE
Microsoft 00000-OEM-0000000-00000
4.5

Display

Intel(R) 810 Chipset Graphics Driver
[Display adapter]
Tatung 2025 [Monitor] (13.8"vis, April 1998)

Multimedia

Gameport Joystick (no joystick connected)
YAMAHA DS-XG Legacy Sound System
YAMAHA DS-XG PCI Audio CODEC

Other Devices

Avantis CD-ROM Controller
PC/AT Enhanced Keyboard (101/102-Key)
PS2 (PS/2) [Mouse]
USB Root Hub

Software Versions

2simple Software - 2count Version 1.00 * Microsoft Corporation - Microsoft Internet
2simple Software - 2go Version 1.00 * Explorer Version 5.00.2614.3500 *
2simple Software - 2graph Version 1.00 * Microsoft Corporation - Windows
2simple Software - 2paint Version 1.00 * Telephony Version 4.10.2000 *
2simple Software - 2publish Version 1.00 Microsoft Corporation - Windows®

[*](#)
 2simple Software - 2Simple IVT Version 1.00 [*](#)
 2simple Software - ICT Videos Version 1.00 [*](#)
 ACDSee 32 for Windows 95/NT Version 2, 4, 1, 0 [*](#)
 Adiboo [*](#)
 Adobe Acrobat Version 4.0.000 [*](#)
 Alis Software - Pa3to4 Version 1.1 [*](#)
 America Online, Inc. - AOL Instant Messenger (TM) Version 2.0.996 [*](#)
 AOL Installation [*](#)
 Apple Computer, Inc. - QuickTime for Windows Version 2.1.2.59 [*](#)
 Apple Computer, Inc. MoviePlayer Application Version 3, 0, 0, 1 [*](#)
 Apple Computer, Inc. PictureViewer Application Version 3, 0, 0, 1 [*](#)
 Avantis CD Installation Wizard Version 3.2 [*](#)
 Avantis CDsPlayer Version 3.2 [*](#)
 Avantis Ltd - CDserve Monitor Application Version 3.23 [*](#)
 Avantis Ltd. - CDserve Version 3.2 [*](#)
 Babylon Version 2.0 [*](#)
 Banner Blue Software Incorporated - Microsoft Organization Chart Version 2,0,0,1016 [*](#)
 Belarc, Inc. - BelManage Client Version 6.0c [*](#)
 BVRP Software - PhoneTools 2000 Version 2.12 [*](#)
 Crick Software Ltd - CLICKER 3 Version 3.06.0007 [*](#)
 Cyber Patrol Installation [*](#)
 Discover Internet [*](#)
 DK Multimedia - Children's Encyclopedia Version 1.1.0 [*](#)
 DK Multimedia - Chronicle of the 20th Century Version 1.00\$ [*](#)
 DK Multimedia - The Eyewitness Photogallery Sampler Version 08.02.001 [*](#)
 Dorling Kindersley - EyeWitness Space Version 1.0.0.0 [*](#)
 Eastman Software, Inc., A Kodak Business - Imaging for Windows® Version 1.01.1311 [*](#)
 ECZ.EXE [*](#)
 Electronic Library [*](#)
 Event Reminder [*](#)
 Full Circle Software, Inc. - Talkback Version 1.0 [*](#)
 Fun School Maths [*](#)
 Geniographics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0 [*](#)
 Hewlett-Packard Co. - HP DeskJet A.03.01.03 [*](#)
 Hewlett-Packard Company - HP Printing NetMeeting® Version 3.0 [*](#)
 Microsoft Creative Writer Version 2.0 [*](#)
 Microsoft Creative Writer Viewer Version 2.0 [*](#)
 Microsoft Encarta Version 8.29.00.0912 [*](#)
 Microsoft Excel Version 8.0 [*](#)
 Microsoft Kids Plus! Paint It! Version 1.0.0.0805 [*](#)
 Microsoft Map Version 8.00.00.01203 [*](#)
 Microsoft Money Money Import EXE Version 7.0 [*](#)
 Microsoft Money Version 7.00.0723 [*](#)
 Microsoft Office Binder Version 8.0.3501 [*](#)
 Microsoft Office Version 8.0.3512 [*](#)
 Microsoft Outlook Version 8.0 [*](#)
 Microsoft Photo Editor Version 3.0 [*](#)
 Microsoft PowerPoint for Windows Version 8.0 [*](#)
 Microsoft Windows Scripting Host Version 5.0.531.7 [*](#)
 Microsoft Works for Windows Version 4.00.05.465 [*](#)
 Microsoft(R) Chat(TM) Version 2.5 [*](#)
 Microsoft® Plus! for Windows® 95 Version 4.40.500 [*](#)
 Microsoft® Internet Services Version 6.1.33.0 [*](#)
 Microsoft® Schedule+ for Windows 95(TM) Version 7.0 [*](#)
 Microsoft® Word for Windows® 97 Version 8.0 [*](#)
 My World Version 1.0.003 [*](#)
 NDPS [*](#)
 Netropa Corp. - Multimedia Keyboard Version 0.9.6 [*](#)
 Netropa Corp. - OSD Version 2.42 [*](#)
 Netscape Communications nsnotify Version 4.5 [*](#)
 NETSCAPE Version 4.51 [*](#)
 Novell Client Login for 32-bit Windows Version 1.00.05 [*](#)
 Novell wm95 Version 1, 0, 0, 1 [*](#)
 Nullsoft Winamp Version 2.23 [*](#)
 Packard Bell Free Internet [*](#)
 Packard Bell Navigator Version 1.0.12.1 [*](#)
 Packard Bell NEC - PB SoftBar Version 2.4 [*](#)
 Packard Bell NEC - SOS Version 1.0.0.0 [*](#)
 Penguin Hutchinson Reference Suite [*](#)
 PhotoStudio Lite [*](#)
 PhotoStudio Registration [*](#)
 PrintMaster Gold Publishing Suite [*](#)
 PrintMaster Web Site [*](#)
 RealNetworks, Inc. - RealPlayer (32-bit) Version 6.0.5.27 [*](#)
 Seagate Software, Inc. - Backup [*](#)
 Space [*](#)
 Symantec Core Technology Version 20.0.0.197 [*](#)

System for Windows Version 1998.0818.1740ä ä ä ! *	Symantec Corporation - Norton AntiVirus Core Technology Version 5.3.0.156 *
Hutchinson Multimedia Encyclopedia 1996 *	Symantec Corporation - Norton AntiVirus Version 5.3.0.25 *
Icq99 Installation *	Textease *
IDT Corporation - Net2Phone Version 9.0 *	The Learning Company - Reader Rabbit's Key Stage 1, Year 2 Version 1.01 *
InstallShield unInstaller Version 2.20.926.0 *	The Learning Company - Reader Rabbit's Math Ages 6-9 Version 1.00 *
Knowledge Assistant *	TopStudio - EasyCrypto Version 2000 *
Logitech Inc. - MouseWare Version 8.21 *	Update Your Packard Bell PC *
Logotron - PicturePoint Version 1.0.001 *	WaterGate Software Inc. - PC-Doctor For Windows 3.0 Version 3.0 *
Macromedia Director Version 5.0 *	WP Link *
Macromedia Director Version 6.0.2 *	
Macromedia Director Version 7.0.2 *	
Magicland *	
Max Wainewright - 2question Version 1.00 *	
Microsoft Corporation - Clip Gallery 3.0 for Windows Version 3.0 *	
Microsoft Corporation - DirectShow Version 6.01.05.0130 *	

* Click to see where software is installed.

- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.

Legal notice. U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name:Pc25 (in WORKGROUP)

Profile Date:Monday, June 23, 2003 14:43:37

Advisor Version:6.0c

Windows Logon:admin

Operating System

Windows 98 SE (build 4.10.2222)

Processor ^a

1800 megahertz Intel Pentium 4
8 kilobyte primary memory cache
256 kilobyte secondary memory cache

Drives

39.98 Gigabytes Usable Hard Drive Capacity
38.83 Gigabytes Hard Drive Free Space
AVANTIS CDSERVE [CD-ROM drive]
HL-DT-ST CD-ROM GCR-8480B
Generic floppy disk drive (3.5")

Generic IDE hard disk drive (39.98 GB)
-- drive 0

Logins

No details available

System Model

IBM 67922HG
System Serial Number: KB0KFR7

Main Circuit Board ^b

Board: IBM IBM
Bus Clock: 100 megahertz
BIOS: IBM 20KT34AUS 04/24/2002

Memory Modules ^{c,d}

256 Megabytes Installed Memory

Slot 'J6J1' has 256 MB
Slot 'J6J2' is Empty
Slot 'J7J1' is Empty

Local Drive Volumes

c: (on drive 0)	31.44 GB	30.35 GB free
d: (on drive 0)	8.54 GB	8.47 GB free

Network Drives

mounted by admin at 06/23/03
14:43:31

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Installed Microsoft Hotfixes

No details available

Printers

HP Color on
LaserJet 4550 \\SMRCP\HP_COLOUR

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

PCL 6
HP LaserJet
2100 Series on HPLaserJet2100Series
PCL 6

Controllers

Standard Floppy Disk Controller
Intel(R) 82801BA Ultra ATA Storage
Controller - 244B
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)

Display

NVIDIA Vanta/Vanta LT/Vanta PCI
(IBM) [Display adapter]
Sony CPD-E230 [Monitor] (16.1"vis, s/n
6059444, March 2002)

Bus Adapters

Intel(R) 82801BA/BAM USB Universal
Host Controller - 2442
Intel(R) 82801BA/BAM USB Universal
Host Controller - 2444

Multimedia

SoundMAX Integrated Digital Audio

Communications

Intel(R) PRO/100 VE Desktop
Connection
Network Card MAC Address:
00:09:6B:64:43:3C
Network IP Address: 172.19.44.32 / 24

Other Devices

Avantis CD-ROM Controller
Standard 101/102-Key or Microsoft
Natural Keyboard
USB Root Hub
USB Root Hub

Software Licenses

Microsoft - MS 53491-270-3333995-
Office 97 01098
Professional
50578-270-0113986-
Microsoft - 03872 (Key: W7XTC-
Windows 98 SE 2YWFB-K6BPT-
GMHMV-B6FDY)

Software Versions

Adobe Acrobat Reader Version 5.0.0.0*	Microsoft Excel Version 8.0a*
Apple Computer, Inc. - QuickTime	Microsoft imgstart Version 1, 0, 0, 1*
QuickTime 5.0.2*	Microsoft Map Version 8.00.00.01621*
Avantis CD Installation Wizard Version	Microsoft Office Binder Version 8.0.3501
3.2*	*
Avantis CDsPlayer Version 3.2*	Microsoft Office Version 8.0.3512*
Avantis Ltd - CDserve Monitor	Microsoft Outlook Version 8.0*
Application Version 3.23*	Microsoft Outlook Version 8.02*
Avantis Ltd. - CDserve Version 3.2*	Microsoft Photo Editor Version 3.0*
Banner Blue Software Incorporated -	Microsoft PowerPoint for Windows
Microsoft Organization Chart Version	Version 8.0*
2,0,0,1016*	Microsoft Windows Scripting Host
Belarc, Inc. - BelManage Client Version	Version 5.0.531.7*
6.0c*	Microsoft® Plus! for Windows® 95
Centrinity Inc. - FirstClass® Client	Version 4.40.500*
Version 7.008*	Microsoft® Access Version 8.0.4122*
Eastman Software, Inc., A Kodak Business	Microsoft® Find Fast Version 8.0*
- Imaging for Windows® Version	Microsoft® Schedule+ for Windows
1.01.1311*	95(TM) Version 7.5*
Garden!*	Microsoft® Word for Windows® 97
GENI Application Version 2, 0, 0, 1*	Version 8.0*

Genigraphics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0 *	MindVision - Installer VISE 2.8.3 Version 2.8.3 *
Hewlett-Packard - Bierfass II Version 3.001.077.0 *	NDPS *
Junior Control Insight Version 1.03 *	Newman College - Bounce Version 1.00 *
Macromedia Director Version 7.0.2 *	Novell Client Login for 32-bit Windows Version 1.00.05 *
Macromedia, Inc. - Flash 4.0 Version 4,0,7,0 *	Novell wm95 Version 1, 0, 0, 1 *
Maths Explorer *	Sherston Software Playbook *
Microsoft Corporation - Clip Gallery 3.0 for Windows Version 3.0 *	
Microsoft Corporation - DirectShow Version 6.01.05.0130 *	
Microsoft Corporation - Microsoft Internet Explorer Version 5.00.2614.3500 *	

* Click to see where software is installed.

- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.

[Legal notice](#). U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name: Pc26 (in WORKGROUP)

Profile Date: Monday, June 23, 2003 15:14:09

Advisor Version: 6.0c

Windows Logon: admin

Operating System

Windows 98 SE (build 4.10.2222)

Processor ^a

1800 megahertz Intel Pentium 4
8 kilobyte primary memory cache
256 kilobyte secondary memory cache

Drives

39.98 Gigabytes Usable Hard Drive Capacity
38.89 Gigabytes Hard Drive Free Space
AVANTIS CDSERVE [CD-ROM drive]
HL-DT-ST CD-ROM GCR-8480B
Generic floppy disk drive (3.5")

Generic IDE hard disk drive (39.98 GB)
-- drive 0

Logins

No details available

System Model

IBM 67922HG
System Serial Number: KB0KMR9

Main Circuit Board ^b

Board: IBM IBM
Bus Clock: 100 megahertz
BIOS: IBM 20KT34AUS 04/24/2002

Memory Modules ^{c,d}

256 Megabytes Installed Memory

Slot 'J6J1' has 256 MB
Slot 'J6J2' is Empty
Slot 'J7J1' is Empty

Local Drive Volumes

c: (on drive 0)	31.44 GB	30.41 GB free
d: (on drive 0)	8.54 GB	8.47 GB free

Network Drives

mounted by admin at 06/23/03
15:14:04

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Installed Microsoft Hotfixes

No details available

Printers

HP Color on
LaserJet 4550 \\SMRCP\HP_COLOUR

[Click here](#) to see all available security Hotfixes.

- Marks a HotFix that verifies correctly
- Marks a HotFix that fails verification (Failing hotfixes need to be reinstalled)
- An unmarked HotFix lacks the data to allow verification

Controllers

Standard Floppy Disk Controller
Intel(R) 82801BA Ultra ATA Storage Controller - 244B
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)

Bus Adapters

Intel(R) 82801BA/BAM USB Universal Host Controller - 2442
Intel(R) 82801BA/BAM USB Universal Host Controller - 2444

Communications

Intel(R) PRO/100 VE Desktop Connection
Network Card MAC Address: 00:09:6B:D4:41:9C
Network IP Address: 172.19.44.33 / 24

Display

NVIDIA Vanta/Vanta LT/Vanta PCI (IBM) [Display adapter]
Sony CPD-E230 [Monitor] (16.1"vis, s/n 6059446, March 2002)

Multimedia

SoundMAX Integrated Digital Audio

Other Devices

Avantis CD-ROM Controller
Standard 101/102-Key or Microsoft Natural Keyboard
USB Root Hub
USB Root Hub

Software Licenses

Microsoft - MS Office 97 Professional
53491-270-3333995-01098
50578-270-0113986-03872 (Key: W7XTC-Windows 98 SE 2YWFB-K6BPT-GMHMV-B6FDY)

Software Versions

Adobe Acrobat Reader Version 5.1.0.0*	Microsoft Map Version 8.00.00.01621*
Adobe Systems AdobeDownloadManager Version 1.1 *	Microsoft Office Binder Version 8.0.3501*
Avantis CD Installation Wizard Version 3.2*	Microsoft Office Version 8.0.3512*
Avantis CDsPlayer Version 3.2 *	Microsoft Outlook Version 8.0 *
Avantis Ltd - CDserve Monitor Application Version 3.23 *	Microsoft Outlook Version 8.02*
Avantis Ltd. - CDserve Version 3.2 *	Microsoft Photo Editor Version 3.0 *
Banner Blue Software Incorporated - Microsoft Organization Chart Version 2,0,0,1016*	Microsoft PowerPoint for Windows Version 8.0 *
Belarc, Inc. - BelManage Client Version 6.0c *	Microsoft Windows Scripting Host Version 5.0.531.7*
Eastman Software, Inc., A Kodak Business - Imaging for Windows® Version 1.01.1311 *	Microsoft® Plus! for Windows® 95 Version 4.40.500 *
Garden! *	Microsoft® Access Version 8.0.4122 *
Geniographics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0*	Microsoft® Find Fast Version 8.0*
	Microsoft® Schedule+ for Windows 95(TM) Version 7.5*
	Microsoft® Word for Windows® 97 Version 8.0 *
	NDPS *
	Newman College - Bounce Version 1.00*

Hewlett-Packard - Bierfass II Version
3.001.077.0 [*](#)

Macromedia, Inc. - Flash 4.0 Version
4,0,7,0 [*](#)

Maths Explorer [*](#)

Microsoft Corporation - Clip Gallery 3.0
for Windows Version 3.0 [*](#)

Microsoft Corporation - DirectShow
Version 6.01.05.0130 [*](#)

Microsoft Corporation - Microsoft Internet
Explorer Version 5.00.2614.3500 [*](#)

Microsoft Excel Version 8.0a [*](#)

Microsoft imgstart Version 1, 0, 0, 1 [*](#)

Novell Client Login for 32-bit Windows
Version 1.00.05 [*](#)

Novell wm95 Version 1, 0, 0, 1 [*](#)

Sherston Software Playbook [*](#)

* Click to see where software is installed.

a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.

b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.

c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.

d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.

[Legal notice](#). U.S. Patents 6085229, 5665951 and Patents pending.

Computer Profile Summary

Computer Name: Pc36 (in WORKGROUP)

Profile Date: Monday, June 23, 2003 16:04:38

Advisor Version: 6.0c

Windows Logon: admin

Operating System

Windows 98 SE (build 4.10.2222)

Processor ^a

2000 megahertz Intel Pentium 4
8 kilobyte primary memory cache
512 kilobyte secondary memory cache

Drives

39.98 Gigabytes Usable Hard Drive Capacity
38.97 Gigabytes Hard Drive Free Space
AVANTIS CDSERVE [CD-ROM drive]
HL-DT-ST DVD-ROM GDR8161B [CD-ROM drive]
Generic floppy disk drive (3.5")
Generic IDE hard disk drive (39.98 GB)
-- drive 0

Logins

No details available

Installed Microsoft Hotfixes

No details available

[Click here](#) to see all available security Hotfixes.

Marks a HotFix that verifies correctly

System Model

IBM 67923JG
System Serial Number: KBOVKF4

Main Circuit Board ^b

Board: IBM IBM
Bus Clock: 100 megahertz
BIOS: IBM 20KT38AUS 09/19/2002

Memory Modules ^{c,d}

256 Megabytes Installed Memory

Slot 'J6J1' has 256 MB
Slot 'J6J2' is Empty
Slot 'J7J1' is Empty

Local Drive Volumes

c: (on drive 0)	31.44 GB	30.50 GB free
d: (on drive 0)	8.54 GB	8.47 GB free

Network Drives

mounted by admin at 06/23/03
16:04:33

f: \\smrcp\sys	507 MB	333 MB free
g: \\smrcp\vol1	8.09 GB	4.41 GB free
h:	8.09 GB	4.41 GB free
\\smrcp\vol1\shared	GB	free
z: \\smrcp\sys	507 MB	333 MB free

Printers

Canon BJC-610 (Raster) on LPT1:
Canon S300 on USBPRN01
HP Color LaserJet 4550 on \\SMRCP\HP_COLOUR PCL 6

☐ Marks a HotFix that fails verification
(Failing hotfixes need to be reinstalled)
An unmarked HotFix lacks the data to
allow verification

HP LaserJet
2100 Series on HPLaserJet2100Series
PCL 6

Controllers

Standard Floppy Disk Controller
Intel(R) 82801BA Ultra ATA Storage
Controller - 244B
Primary IDE controller (dual fifo)
Secondary IDE controller (dual fifo)

Display

NVIDIA Vanta/Vanta LT/Vanta PCI
(IBM) [Display adapter]
Sony CPD-G220 [Monitor] (16.1"vis, s/n
3209008, July 2001)

Bus Adapters

Intel(R) 82801BA/BAM USB Universal
Host Controller - 2442
Intel(R) 82801BA/BAM USB Universal
Host Controller - 2444

Multimedia

SoundMAX Integrated Digital Audio

Communications

Intel(R) PRO/100 VE Desktop
Connection
Network Card MAC Address:
00:09:6B:F2:AC:C4
Network IP Address: 172.19.44.37 / 24

Other Devices

Avantis CD-ROM Controller
Standard 101/102-Key or Microsoft
Natural Keyboard
USB Root Hub
USB Root Hub

Software Licenses

Microsoft - MS 53491-270-3333995-
Office 97 01098
Professional
50578-270-0113986-
Microsoft - 03872 (Key: W7XTC-
Windows 98 SE 2YWFB-K6BPT-
GMH MV-B6FDY)

Software Versions

Avantis CD Installation Wizard Version 3.2*	Microsoft Excel Version 8.0a*
Avantis CDsPlayer Version 3.2*	Microsoft imgstart Version 1, 0, 0, 1*
Avantis Ltd - CDserve Monitor Application Version 3.23*	Microsoft Map Version 8.00.00.01621*
Avantis Ltd. - CDserve Version 3.2*	Microsoft Office Binder Version 8.0.3501*
Banner Blue Software Incorporated - Microsoft Organization Chart Version 2,0,0,1016*	Microsoft Office Version 8.0.3512*
Belarc, Inc. - BelManage Client Version 6.0c*	Microsoft Outlook Version 8.0*
Canon BJ Printer Driver Installer Version 4,1,0,950*	Microsoft Outlook Version 8.02*
Canon BJ Printer Driver Version 7.1.0.001*	Microsoft Photo Editor Version 3.0*
Canon BJ Raster Printer Driver Version 5.1.1.950*	Microsoft PowerPoint for Windows Version 8.0*
Eastman Software, Inc., A Kodak Business - Imaging for Windows® Version 1.01.1311*	Microsoft Windows Scripting Host Version 5.0.531.7*
Garden!*	Microsoft® Plus! for Windows® 95 Version 4.40.500*
Geniographics®, An In Focus Systems® Company - GraphicsLink(TM) for Windows Version 8.0*	Microsoft® Access Version 8.0.4122*
Hewlett-Packard - Bierfass II Version	Microsoft® Find Fast Version 8.0*
	Microsoft® Schedule+ for Windows 95(TM) Version 7.5*
	Microsoft® Word for Windows® 97 Version 8.0*
	NDPS*
	Newman College - Bounce Version 1.00*
	Novell Client Login for 32-bit Windows Version 1.00.05*

[3.001.077.0](#) *
[Macromedia Director Version 7.0.2](#) *
Macromedia, Inc. - Flash 4.0 Version
[4,0,7,0](#) *
[Maths Explorer](#) *
Microsoft Corporation - Clip Gallery 3.0
for Windows Version [3.0](#) *
Microsoft Corporation - DirectShow
Version [6.01.05.0130](#) *
Microsoft Corporation - Encarta
Encyclopedia Version [9.0.0.0710](#) *
Microsoft Corporation - Microsoft Internet
Explorer Version [5.00.2614.3500](#) *

Novell [wm95 Version 1, 0, 0, 1](#) *
Sherston Software [Playbook](#) *

* Click to see where software is installed.

- a. Megahertz measurement may be inaccurate if other programs were busy during last analysis.
- b. Data may be transferred on the bus at one, two, or four times the Bus Clock rate.
- c. Memory slot contents may not add up to Installed Memory if some memory is not recognized by Windows.
- d. Memory slot contents is reported by the motherboard BIOS. Contact system vendor if slot contents are wrong.

Copyright 2000-3, Belarc, Inc. All rights reserved.

[Legal notice](#). U.S. Patents 6085229, 5665951 and Patents pending.

Recommendations



- ✍ Replace the ICT Server.
- ✍ Reload old server and re-deploy.
- ✍ Back up all data on server and migrate information across to new System.
- ✍ Reload all PC's from the ICT Room and Re-deploy throughout the school.
- ✍ PC's – Compaq no4 & IBM no8 do not work at all.
- ✍ We strongly recommend replacing all ICT Room PC's with new systems. All new systems should run either Windows 2000 or XP. (We recommend reloading and reconfiguring some of the better specification PC's for re-deployment with-in the school). There is a total of 15 PC's in the ICT Room.
- ✍ PC21 in Class 1F, PC15 in Class 4E, PC16 in Class 4/3G, PC17 in Class 3H, PC18 in Class 6H, PC19 in Class 5H, PC22 in Class R1 all need replacing; we could replace these with the refurbished systems from the ICT Room.
- ✍ Implement serial numbering system for each Workstation, Server, Peripheral etc to help problem logging and solutions.

Other information still required

- ✍ ISP dial-up number & technical support telephone number.
- ✍ Telephone number for router & router information.
- ✍ Hub details.
- ✍ Full audit on staff / Admin workstations.

We believe this work is imperative for the safe operation and successful support of the schools ICT room and network.